3160-5 (August 1999)

UNITED STATES

DEPARTM BUREAU (

FORM APPROVED

| | NO. 1004 | | |
|----------|----------|-----|-----|
| Expires: | November | 30, | 200 |
| | | _ | |

| MITED STATES MENT OF THE INTERIOR | OMB NO. 1004-0135 Expires: November 30, 2000 |
|-----------------------------------|---|
| OF LAND MANAGEMENT | 5. Lease Serial No. |

| SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. | | | | NMNM30585 - 6. If Indian, Allottee or | | |
|---|--|--|--|--|---|-------------------------|
| SUBMIT IN TRIPLICATE - Other instructions on reverse side. | | | | 7. If Unit or CA/Agree | ment, Name and/or No. | |
| 1. Type of Well | | | | | 8. Well Name and No. CARRACAS 24 B | 1 |
| Oil Well Gas Well Other 2. Name of Operator Contact: MARY CORLEY | | | | | 9. API Well No. | |
| BP AMERICA PRODUCTION CO E-Mail: coi | | E-Mail: corleym | • | | 30-039-24652-00-S1 10. Field and Pool, or Exploratory | |
| 3a. Address P. O. BOX 3092 HOUSTON, TX 77253 | | 3b. Phone No. (include area code) Ph: 281.366.4491 Fx: 281.366.0700 | |) | BASIN FRUITLAND COAL | |
| 4. Location of Well (Footage, Sec., T | ., R., M., or Survey Description | 1) | | | 11. County or Parish, a | |
| Sec 24 T32N R4W NENE 079 36.97737 N Lat, 107.19972 W | / Lon | | | | RIO ARRIBA CO | |
| 12. CHECK APPE | ROPRIATE BOX(ES) TO | O INDICATE | NATURE OF 1 | NOTICE, R | EPORT, OR OTHEI | R DATA |
| TYPE OF SUBMISSION | | | ТҮРЕ О | F ACTION | | |
| | ☐ Acidize | Deep | en | □ Produc | tion (Start/Resume) | ☐ Water Shut-Off |
| Notice of Intent | Alter Casing | _ | ure Treat | □ Reclam | ation | □ Well Integrity |
| ☐ Subsequent Report | Casing Repair | □ New | Construction | □ Recom | | □ Other |
| Final Abandonment Notice | Change Plans | | and Abandon | _ | rarily Abandon | |
| 13. Describe Proposed or Completed Op | Convert to Injection | □ Plug | | □ Water I | | |
| 13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Addetermined that the site is ready for it Corrected Sundry BP America Production Compas per the following procedur Notify regulatory agencies (Bi in advance of plugging activit 1. Check anchors. MIRU wor 2. Check and record tubing, c 3. Blow down wellhead. If ne 4. Nipple down WH. NU BOF 5. TOH with 2-3/8" tubing. If workstring to spot cement plug 6. Spot 400' cement plug (55) | ork will be performed to provide the operations. If the operation rebandonment Notices shall be final inspection.) pany respectfully request e: LM-505-599-8907) and (Notices and the control of the con | permission to NMOCD-Charlment for all cer pressures. water. so 500 psi. h, LD production, LD production, LD production, LD set at 2870'kb above CIBF | e completion or recequirements, inclusion plug and abande Perrin 505-3 ment plugs. On tubing and F kb (2858' md). | don the subject of th | new interval, a Form 316 on, have been completed, ject well 24 hours n System | 0-4 shall be filed once |
| c | Electronic Submission For BP AMERIC Committed to AFMSS for pr | 'A DOMNIICTIM | N CO, sent to the eve Mason on 1 | ne Farmingto 10/21/2002 (0: | SSXM0035SE) | |
| Name (Printed/Typed) MARY CORLEY | | Title AUTHORIZED REPRESENTATIVE | | | | |
| Signature (Electronic | Submission) | | Date 10/21/ | 2002 | | |
| | THIS SPACE F | OR FEDERA | L OR STATE | OFFICE U | JSE | |
| | gned: Stephen Mason | | Title | | | 11/5/UZ Date |
| Conditions of approval, if any, are attachertify that the applicant holds legal or ewhich would entitle the applicant to conditions. | quitable title to those rights in t | es not warrant or the subject lease | Office | | | |

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #15352 that would not fit on the form

32. Additional remarks, continued

7. TOH to 2543' kb. Spot 350' balanced plug (48 cu ft) from 2193' - 2543' kb across Ojo Alamo.

78. TOH to 150' kb. Spot 150' plug (21 cu. Ft) from 150' kb to surface.

9. LD 2-3/8" workstring.

10. ND BOPs. Cut off casing and wellhead. Install P&A marker.

11. Rehabilitate location according to BLM/NMOCD regulations.

plug 1152-1052' comer Nucimiento

plug 354'-254' coner Surface casing shoe.