

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

Name of Operator
Taurus Exploration, Inc.

Address and Telephone No.
2198 Bloomfield Highway; Farmington, NM 87401

Location of Well (Footage, Sec., T., R., M., or Survey Description)
1169' FNL, 1173' FWL, Sec. 25, T32N, R6W, N.M.P.M.

5. Lease Designation and Serial No.

SF-079011

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

San Juan 32-5 Unit

8. Well Name and No.

San Juan 32-5 Unit #6A

9. API Well No.

30-039-25901

10. Field and Pool, or exploratory Area

Blanco MV/Basin DK

11. County or Parish, State

Rio Arriba NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Completion
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9/12/98 TIH and clean out sand w/air. Mill out CIBP @ 5500'. Strong gas flow from well. Clean out to 5920". Could not circulate @ 2100 psi. TOH to 4750" SDFN.
9/14/98 TOH. Found tubing - twisted off and charred. Had downhole fire. Left mill, bit sub and 16' tubing in hole. TIH w/mill. Found 30' fill on fish. Milled 3.5' SDFN.
9/15/98 TIH and mill on fish. Quit making progress. TOH. Mill worn out. TIH w/overshot. SDFN.
9/16/98 TIH and tag @ 5683'. Wash clean to top of fish @ 5689'. Pushed fish down hole 3'. TOH. No recovery. TIH with concave mill. SDFN.
9/17/98 TIH w/mill. Tag @ 5677'. Circulate to top of fish @ 5692'. Milled 4' and mill quit. TOH. SDFN.
9/18/98 TOH. Mill worn out. TIH w/mill. No fill on fish. Milled 5', then torqued up. Stuck pipe. No movement. Ran freepoint and backed off @ 5659'. Left 1 drill collar, jars and mill in hole. (52') TOH.
9/19/98 TOH. TIH w/jars and drill collars. Tag @ 5629'. Circulate down to fish w/air. Screen into fish. Jar on fish 4 hours. No movement. Backed off of fish. TOH. SDFN.
9/21/98 TOH. TIH w/washpipe, jars and 6 drill collars. Tag sand @ 5650'. Wash down to 5663'. TOH. Wash shoe worn out. SDFN.
9/22/98 TIH w/washpipe. Tag top of fish @ 5659'. Wash over to 5688'. Quit milling. TOH. Recovered drill collar stuck in washpipe. SDFN.
9/23/98 TIH w/washpipe. Tag @ 5684'. Wash over 1'. No progress. TOH. Shoe worn bad on outside. SDFN.
9/24/98 TIH w/washpipe, jars and 6 collars. Tag @ 5684'. Mill for 4 hours w/good circulation. Lost circulation. Picked up 6' and was stuck. SDFN.
9/25/98 Run freepoint. Could not get inside collars. Cut off tubing @ 5429'. TOH. TIH w/overshot and jars. Jar on fish. Slipped off of fish. TOH. Fishing tools packed with sand.

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Production Superintendent

Date 10/21/98

(This space for Federal or State office use)

Approved by _____ Title _____

Conditions of approval, if any:

ACCEPTED FOR RECORD

NOV 03 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

FARMINGTON DISTRICT OFFICE

UNOC