In Lie	u of
Form	3160
(June	1990)

## UNITED STATES DEPARTMENT OF INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED		
Budget Bureau No. 1004-0135		
Expires: March 31, 1993		

5.	Lease Designation and Serial I	
BECENTA	Budget Bureau No. 1004-0 Expires: March 31, 199	

SUNDRY NOTICE	AND REPORTS	ON WELLS
SOMET NOTICE		O11 11 DDD0

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

UZUNAPRIEBATION AH	<del> </del>
--------------------	--------------

	Lease Designation and Serial P	4(
_	 SF-078772	

	TO DRILL" for permit for such proposals	6.	If Indian, Allottee or Tribe Name
		ON, NA	
	SUBMIT IN TRIPLICATE	7.	If Unit or CA, Agreement Designation
۱.	Type of Well Oil Well X Gas Well Other	8.	Well Name and No. ROSA UNIT #91C
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	9.	API Well No. 30-039-26991
3.	Address and Telephone No. PO BOX 3102 MS 25-1, TULSA, OK 74101 (918) 573-6254	10.	Field and Pool, or Exploratory Area BLANCO MV
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) 2530' FNL & 2530' FEL, SW/4 NE/4 SEC 35-32N-06W	11.	County or Parish, State RIO ARRIBA, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
X Subsequent Report	Plugging Back	Non-Routine Fracturing	
1	Casing Repair	Water Shut-Off	
Final Abandonment	Altering Casing	Conversion to Injection	
	Other Completion	Dispose Water	
		(Note: Report results of multiple completion	
		on Well Completion or Recompletion Report	
		and Log form.)	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well 13. is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

08/23/2002 MIRU, Spotted equipment. Rec'd & tallied tbg. Secure location

08/26/2002 RU& RIH w/ 196 Jts 2 3/8" tbg. Circ well, pressure test to 3500 psi & spotted 500 gal acid across PLO (5895'). Pressure test lines to 4500 psi. RU WL to perf 34 (0.38") holes across PLO top down at the following intervals: 5625', 31', 32', 34', 36', 37', 40', 47', 51', 66', 71', 73', 79', 83', 85', 88', 90', 92', 95', 99', 5702', 13', 19', 28', 30', 34', 36', 72', 77', 83', 99', 5847', 5934' & 49'. Had to make an extra TIH to complete all perfs. PBTD @ 6011'. Secure location

08/27/2002 Ball off PLO w/ 24 bbl 15% HCI & 60 ball sealers. Ball action good & complete. Recover 59 balls w/ 29 hits. Frac PLO w/ 80,000# 20/40 Ariz sand @ 95 BPM, 3100psi. Set CIBP @ 5610', loaded hole & pressure test 3500 psi. Spotted 20 gal 28% HCl across bottom perfs. Perf CH-M w/ 17 (0.38") holes @ each of the following intervals: 4804', 06', 5368', 70', 5410', 49', 77', 79', 81', 89', 91', 94', 96', 5583', 85', 98', & 99. Ball off CH-M w/ 24 bbl 15% HCl. Recover 25 balls w/ 17 hits. Frac CH-M w/ 80,000# 20/40 Ariz sand @ 55 bpm, 3000psi. All sand away. Flushed to top of perfs. RD BJS. RIH w/ tbg to LT & unloaded well w/ air pkg. Secure location

14.	I hereby certify that the foregoing is true and correct  Signed Tracy Ross	Title Production Analyst	Date <u>Sept</u>	embe ACSEPTED FOR RECORL
	(This space for Federal or State office use)		D	SFP 1 0 2002
	Approved by  Conditions of approval, if any:	Title	_ Date	FARMINGTUN FIELD OFFICE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

