UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Sureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT				
SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Sarial No.		
		820780970		
Do not use this form for proposals to drill or to de Use "APPLICATION FOR PERMIT	epen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name		
Use "APPLICATION FOR FERMIN	100 Such proposals			
		7. If Unit or CA. Agreement Designation		
. Type of Well				
Oil Sas Other		8. Well Name and No.		
. Name of Operator	Attention:	Heaton Com A LS 13		
AMOCO PRODUCTION COMPANY	Lois Raeburn	3004510087		
3. Address and Telephone No.	(303) 830-5294	10. Field and Pool, or Exploratory Area		
P.O. Box 800, Denver, Colorado 80201		Astec/ Pictured Cliffs		
Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State		
1750FSL 1650FEL Sec.	32 T 31N R 11W Unit J	San Juan New Mecico		
CHECK APPROPRIATE BOX(s) TO	O INDICATE NATURE OF NOTICE, F	REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION			
TTPE OF SUBMISSION				
57	Abandonment	Change of Plans		
Notice of Intent	Recompletion	New Construction Non-Routine Fracturing		
Subsequent Report	Plugging Back Casing Repair	Water Shut-Off		
	Altering Casing Other Bradenhead	Conversion to Injection		
Final Abandonment Notice	(Note: Rec	」 Dispose Water port results of multiple completion on Well Completion or		
	Recomplet	tion Report and Log form.)		
13. Describe Proposed or Completed Operations (Clearly state all pertinent d	etails, and give pertinent dates, including estimated date of startingers and tones pertinent to this work.)*	ng any proposed work . If well is directionally drilled, give		
subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Amoco Production Company request permission to repair the Bradenhead leak on the above mentioned well.				
Affice Frederich Company requise parimeters to the				
See attached Procedures				
If you should have any questions please call M	lark Rothenburger @ (303) 830-5612			
II you should have any questions process	-			
	The Earling Store	Range A. Commission of the Com		
	DEGETV			
	(3) 			
	* f 			
	Dia skar -			
	OR COME	海沟 - 11 8		
	DMG. 3			
7				
14. I hereby certify that the foregoing is true and correct	/ Business As	ssistant Date01-05-1995		
Signed AND MULTINATION	Title Busiless As			
(This space for Federal or State office use)				

Approved by
Conditions of approval, if any:

APRROVEW

37 JAN 09 1925

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any raise in the Control of the United States and raise in the Control of the C

Heaton Com A LS 13 J 32 31N - 11W 30-045-1008700:PC

Bradenhead Procedure (1/4/95)

- 1. Record TP, SICP, and SIBHP.
- 2. MIRUSU.
- 3. TOH with 1 1/4" tubing (check condition of tubing).
- 4. RIH with RBP and set at 1550'.
- 5. Run CBL and fax to Mark Rothenberg (Denver, 303-830-4276)
- 6. Perforate 2 squeeze holes within 100' of TOC (1320' from Temp. Survey '57).
- 7. Attempt to circulate to surface, and conduct a cement squeeze with adequate cement. Drill out cement.
- 8. TOH with RBP
- 9. Clean out to PBTD (2320')
- 10. RIH with 1 1/4" tubing.
- 11. Tie well back into surface equipment and turn over to production.

		Amoco Production Company ENGINEERING CHART	Sneet No
SUBJECT	Heston Com LS (5/57)		Date
150'		8 5/8", 24 = , -3 - 5 5	• .
			Ojo Alamo undereloped. - Kirkland Top 986'
		Toc = 1320'	(Temp Survey 5/57) - FT TOD 18661
			- PC 700 2269
2313'	2270	1 /4", 2.3 # Grade &	3
23201 23801	PBTD	5 1/2" , 15,5 # , 5-5	5