

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R14

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

14-20-604-1951

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo-Ute Mountain

7. UNIT AGREEMENT NAME

Horseshoe Gallup Unit

8. FARM OR LEASE NAME

Horseshoe Gallup

9. WELL NO.

212

10. FIELD AND POOL, OR WILDCAT

Horseshoe Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 34-31N-16W

12. COUNTY OR PARISH

San Juan

13. STATE New Mexico

1. OIL WELL [X] GAS WELL [ ] OTHER [ ]

2. NAME OF OPERATOR Atlantic Richfield Company

3. ADDRESS OF OPERATOR 1860 Lincoln Street, Suite 501, Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.) At surface Unit M, 445' f/South & 202' f/West lines Section 34

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5402' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF [ ] PULL OR ALTER CASING [ ] FRACTURE TREAT [ ] MULTIPLE COMPLETE [ ] SHOOT OR ACIDIZE [ ] ABANDON\* [ ] REPAIR WELL [ ] CHANGE PLANS [ ] (Other) [ ]


SUBSEQUENT REPORT OF:

WATER SHUT-OFF [ ] REPAIRING WELL [ ] FRACTURE TREATMENT [ ] ALTERING CASING [ ] SHOOTING OR ACIDIZING [ ] ABANDONMENT\* [ ] (Other) Shut In, Extension Request [ ]

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Production from this well declined to 2 BOPD and it was not economical to operate. The well was shut in May 1973. This well is in a large Unit which is now under waterflood operations. Future plans are to conduct waterflood and tertiary studies. These studies may result in a revised waterflood plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.



TEMPORARY ABANDONMENT

EXPIRES JUN 1 1977

Two copies sent to New Mexico Oil Conservation Commission

18. I hereby certify that the foregoing is true and correct

SIGNED W. A. Walther, Jr. TITLE Operations Manager

DATE 6/04/76

This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

TITLE DATE