



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Approval expires _____
Indian Agency Navajo
1-147-DD-7653
Allottee _____
Lease No. _____

RECEIVED
NOV 17 1959

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. Navajo 72 is located 660 ft. from N line and 660 ft. from E line of sec. 34
SE/4 Sec. 34 (1/4 Sec. and Sec. No.) 31N (Twp.) 17W (Range) NM PM (Meridian)
Undesignated (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5220 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6 1/2" hole to 1289'

Top of Dakota 1245'
Water at 1245'

Plugged as follows:

Cement plug from 1289' to 1200'
" " " 660' to 600'
" " " 50' to surface
Mudded between plugs

Erected dry hole marker and sign.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company KING OIL COMPANY
Address 745 Petroleum Club Bldg.
Denver, Colorado

By Bernard King
Title President

100 1/2
200 1/2
300 1/2
400 1/2
500 1/2
600 1/2
700 1/2
800 1/2
900 1/2
1000 1/2