5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR	14,-20-604-1951
GEOLOGICAL SURVEY	6. IEMDIAN, ALLOTTEE OR TRIBE NAME
	Ute Mountain
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug pack to a different reservoir. Use Form 9-331-0 for such proposals.)	Horseshoe Gallup Unit
reservoir, Use Form 9–331–U for such proposals.)	8. FARM OR LEASE NAME
1. oil — gas —	Horseshoe Gallup Unit
well — well — other X - Injection	9. WELL NO.
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of	215
Atlantic Richfield Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 707-17th Street,	Horseshoe Gallup Unit
P.O. Box 5540, Denver, CO 80217	11. SEC., T., R., M., OR BLK, AND SURVEY OF AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit "p"	Sec. 34-31N-16W
	12. COUNTY OR PARISH: 13. STATE
AT SURFACE: 960' FSL & 910' FEL, Sec. 34 AT TOP PROD. INTERVAL: Appx. same	San Juan New Mexico
AT TOTAL DEPTH: Appx. same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	None Assigned
REPORT, OR OTHER DATA	
	15. ELEVATIONS (SHOW DF, KDB, AND WD 5484' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	المنافع كالمائد المنافع المناف
FRACTURE TREAT SHOOT OR ACIDIZE FRACTURE TREAT FRACT	
REPAIR WELL	The part results of multiple completion or zon
MULTIPLE COMPLETE TO TO NOT OUT	diage on Form 9-330.)
CHANGE ZONES	387
CHANGE ZONES	•
(other)	DIV
(other) DIST, 3	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent.)	irectionally drilled give subsurface locations and
ARCO has plugged and abandoned the subject well	i in accordance with the Sundry
Notice dated December 30, 1982, and approved by	y the BLM-MMS on January 13, 19
Injection interval 1378' - 1417' OA,	Gallup fm. Spotted cement plugs
as per the attached plugging operations report	·
Completed P & A, 7-5-83.	
Final restoration will be commenced as soon as	weather permits. An additional
subsequent report will be filed when restoration	on has been completed.
	والمرابع المورد ويتعمل المناف المراف المراف المراف المراف المراف المراف المراف المرافع المرافع المرافع المرافع
	APPROVED TO THE PLUGGING OF THE
1	WELL BORE ONLY. LIABILITY UNDER
·	THE BOND RETAINED UNTIL SURFACE
Subsurface Safety Valve: Manu. and Type 1	RESTORATION IS COMPLETED AND
	APPROVED.
18. I hereby certify that the foregoing is true and correct	Er underhalben dusen – serment derhalben bei der der eine
SIGNED SIGNED FITLE Dist. Prod. Sup	DATE November 30, 1983
(This space for Federal or State offi	
APPROVED BY L. Mark hollis	NOV 03 128/
CONDITIONS OF APPROVAL IF ANY: AREA MAN	
	null
And the second s	
	iide

HSG #215 Horseshoe Gallup Field

P & A OPERATIONS:

MI RU 6/29/83. Well had 550 psi SITP. Obtained permission f/Mr. Howard Lemm, USGS, Grand Junction & sqz'd existing perfs 1378-1417' thru tbg w/15 sx neat cmt. SDFN.

SD f/holiday weekend.

In am no press on tbg. Rel'd pkr. Move pkr dn hole 5' & stack out. Pkr wouldn't rel. Rot to right to rel safety jt. POH w/7 jts. Attempt to run thru-tbg perf gun. Hung up in csg @ 1064'. POH w/WL & tbg. Tbg had twisted off leaving fish f/1216-1064'. Perf 4 holes @ 1064'. Spt 28 sx cmt above perfs. Pull 20 jts tbg. Performed Bradenhead sqz & SDON.

FINAL REPORT - WELL P & A, 7/5/83.

RIH w/sinker bar, tagged TOC @ 704' (360' plug). Shot 2 holes @ 150', pmpd
30 sx cmt & circ out thru bradenhead. Tag TOC @ 23', cut well hd & welded
on dry hole marker. Fin'd up surf plug w/2 sx cmt.

CONDITIONS OF APPROVAL AND ADDITIONAL REQUIREMENTS

- 1. This Subsequent Report of Abandonment (SRA) is approved to the plugging of the well bore only. Liability under the bond is retained until surface restoration is completed and approved.
- 2. Once the dirt work has been completed, the operator will submit Form 3160-5, Sundry Notice, informing the Bureau of Land Management (BLM) of this operation. This Sundry Notice, or Second Subsequent Report of Abandonment (SSRA) will be an acceptance rather than an approval action. (Instruction Memorandum No. CO-87-417).
- 3. Form 3160-5, Sundry Notice, will be submitted when all restoration is completed. This Sundry Notice, or Final Abandonment Notice (FAN), will be submitted only when the site is ready for inspection by an official of the BLM.
- 4. PHASED RELEASE OF BOND LIABILITY After proper plugging of the leasehold's well(s), and after the site has been stabilized and seeded, a percentage of the bond liability can be released. Operators who wish to request partial liability release of a single lease bond may delay filing Form 3160-5, Second Subsequent Report of Abandonment (SSRA) until after the site has been reseeded. In this case, the Sundry Notice should not only detail work that was done but also request partial bond liability release. (Instruction Memorandum No. CO-87-307).