

COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SF-078439
Unit Eg. of Sec. 33

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	<input type="checkbox"/>
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL.....		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 23., 1952

Johnston-Federal
Well No. 4 is located 3430 ft. from [M] line and 790 ft. from [E] line of sec. 33
NE $\frac{1}{4}$, NE $\frac{1}{4}$, Sec. 33 31-N 9-W NMPM
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6211 ft. GR. GL-6203'

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

Ran 160' of 10-3/4" 32.75# Smls. Line Pipe. Landed at 172', cemented with 160 sacks neg. West Cement. Plug pumped to 150', cement circulated to surface.

Closed B.O. Preventer on drill pipe and pressured up on surface pipe (before drilling plug) 500#, held pressure of pipe for 30 minutes, no loss of pressure during 30 minutes, no leaks.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Anderson Prichard Oil Corporation

Address Liberty Bank Building
Oklahoma City, Oklahoma.

By Karl Bashara
Karl Bashara
Title Dist. Foreman.

