Budget Bureau No. 42-R358.4. Approval expires 12-31-60.

Form 9-381 a (Feb. 1951)

Blanco Mesaverde
(Field)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Lease No. SF 078439
Unit Johnston-Federal

SUNDRY NOTICES AND REPORTS ON WELLS

(INDICATE ABOVE BY CHECK MA	RK NAT	URE OF REPORT, NOTICE, OR OTHER DATA)
Notice of Int. to Perforate Tubin	gX	
NOTICE OF INTENTION TO ABANDON WELL		
NOTICE OF INTENTION TO PULL OR ALIER CASING	- 1	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ALTERING CASUAGS. GEOLUGICAL SUBSEQUENT REPORT OF RE-DRILLING OF REDAINGTON, NEW MISSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OF REMAINSTON, WENT
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. SUBSEQUENT REPORT OF ALTERING CASINGS. GEOLOGICAL SUBSEQUENT REPORT OF ALTERING CASINGS.
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF WATER SHUT-OFF JAN 18 SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF

The elevation of the derrick floor above sea level is 6211 ft.

DETAILS OF WORK

31 N 9 W (Range)

San Juan (County or Subdivision)

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Proposal is made to perforate 2-7/8" OD tubing 4550-55 w/20 holes in order to reduce friction loss between tubing-liner Annulus during casing flow.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be combined.

Company ANDERSON-PRICHARD OIL CORPORATION

Address 1740 Broadway

Denver 2, Colorado By /s/ Charles M. Heard

Title District Superintendent



•