



Corporation

## UNION TEXAS PETROLEUM DIVISION

SUITE 1010 LINCOLN TOWER • 1860 LINCOLN STREET • DENVER, COLORADO 80203 • 534-8221



November 18, 1971

H-33-31N-92

Mr. Emery Arnold  
New Mexico Oil Conservation Commission  
1000 Rio Brazos Road  
Aztec, New Mexico 87401

Re: Compressor Installation  
✓ Johnston Federal #4  
Blanco Mesa Verde Field, New Mexico

Dear Sir:

During January 1965, 2 - 100 HP compressors were installed on the captioned well. These proved to be too small and were replaced in February 1965 with 2 - 150 HP units. These units (150 HP) were removed August 1, 1965.

During September 1967 2 - 150 HP compressors were again installed and have remained in service since.

Please advise if any further information is required.

Very truly yours,

D. H. Pickering  
Production Engineer

DHP:dm