

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

LEASE DESIGNATION AND SERIAL NO.  
14-28-684-195  
14-08-0001-8200

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. NAME OF OPERATOR  
ARCO Oil and Gas Company, A Division of Atlantic Richfield  
3. ADDRESS OF OPERATOR  
1816 E. Mojave, Farmington, New Mexico 87401  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

Unit "L" 2140' FSL & 735' FWL

14. PERMIT NO.  
15. ELEVATIONS (Show whether OF, RT, OR, etc.)  
5369' GL

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Navajo-Ute Mountain  
7. UNIT AGREEMENT NAME  
Horseshoe Gallup Unit  
8. FARM OR LEASE NAME  
Horseshoe Gallup  
9. WELL NO.  
201  
10. FIELD AND POOL, OR WILDCAT  
Horseshoe Gallup  
11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA  
Sec. 34, T-31N, R-16W  
12. COUNTY OR PARISH  
San Juan  
13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☒  
REPAIR WELL ☐ CHANGE PLANE ☐  
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

At your request (attached) ARCO Oil and Gas Company plans to plug and abandon the HGU #201. We are, however, requesting a 120 day extension to your March 2 deadline so that a thorough reservoir evaluation can be completed along with co-owner approval. In addition, this extension will allow the work to be done during better weather.

A proposed plugging procedure is included for your review and approval. Once plugging is complete, reseedling will be completed per BLM standards.

RECEIVED  
EEB 11 1987  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED L. Mark Morris

TITLE Area Production Supt.

DATE 2-2-87

(This space for Federal or State office use)

APPROVED BY L. Mark Morris  
CONDITIONS OF APPROVAL, IF ANY:

TITLE ACTING AREA MANAGER

DATE 2-2-1987

\*See Instructions on Reverse Side

**HORSESHOE GALLUP UNIT PRODUCING WELLS  
PLUGGING AND ABANDONMENT PROCEDURE**

- 1) MIRU. RIH below the bottom perforation w/tbg. open ended. Pump sufficient cement inside casing to cover top perforation by 50'.
- 2) POH w/tbg. GIH w/wireline and perforate casing as specified by New Mexico Oil Commission. Number of shots should be sufficient to allow cement squeeze. POH w/wireline. GIH w/tbg. open ended. Squeeze cement to provide plug inside and outside of casing to surface.
- 3) POH w/tbg. Cut casing one foot below ground level. Weld a blind flange to casing, and weld a dry hole marker on blind flange. Fill hole and move off.
- 4) Rehabilitate location and access road using stipulations supplied by the Bureau of Land Management.