Submit 3 copies to Appropriate District Office

State of New Mexicó Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-8

DEGR. Office				Kevise	=u 1-1-09
	CONSERVATIO	ON DIVISION	WELL API NO		
P.O. Box 1980, Hobbs, NM 88240 2040 S. Pacheco			3004510173		
Santa Fe, New Mexico 87505-6429			5. Indicate T	vpe of Lease	
P.O. Box Drawer DD, Artesia, NM 66210				STATE 🗹	FEE 🗌
DISTRICT III. 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No. B-11479		
SUNDRY NOTICES AN	D REPORTS ON WEL	 L		B-114/9	ar el ariente
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
			NEW MEXICO COM M		
1. Type of Well: OIL GAS	<u> </u>		1		
Office Control of the			8. Well No.		
2. Name of Operator FOUR STAR OIL AND GAS COMPANY			8. Well No.	1	
3. Address of Operator 3300 N. Butler Ave., Sui	ite 100 Farmington	NM 87401	9. Pool Name	or Wildcat BLANCO MESA VERDE	
4. Well Location				DENITOO INCOM VENDE	
Unit Letter A : 1190	Feet From TheNORT	TH_Line and 1190	Feet From	The <u>EAST</u> Line	
Section <u>36</u> Township	p T31N R	ange R12W NM	1PM	SAN JUAN COUNTY	
10. Elevi	ation (Show whether DF, RK	(B, RT,GR, etc.) 5882'			
11. Check Appropriat	e Box to Indicate Nat	ure of Notice, Report	, or Other I	Data	
NOTICE OF INTENTION TO:		SL	JBSEQUE	NT REPORT OF:	
	ABANDON	REMEDIAL WORK	Z Z	ALTERING CASING	П
TELL OTHER PERSONS TO THE PERSONS TO		COMMENCE DRILLING OPE		PLUG AND ABANDONMENT	_
		CASING TEST AND CEMEN	_		
PULL OR ALTER CASING OTHER:	П	OTHER:	_	ERDE COMPLETION	✓
OTHEN.		O ITEX.			
12. Describe Proposed or Completed Operations (Canaparage any proposed work) SEE RULE 1103.	Clearly state all pertinent	details, and give pertiner	nt dates, inclu	iding estimated date of sta	rting
FOUR STAR OIL & GAS COMPANY HAS COMPLE	TED THE FOLLOWING O	N THE SUBJECT WELL:			
2/20/98 - MIRU SERVICE UNIT. ND WELLHEAD, FROM 2600' - 4760'. PERFORATE MESA VERDE (SET AT 4747'. SPOT 500 GAL, 15% HCL ACROSS 20/40 SAND. RIH W/ TBG TO 4560'. SWAB WELL.	(PT. LOOKOUT) INTERVA S NEW PERFS. PULL PAC	L FROM 4640' - 4660' W/	4 SPF, DEEP	CHARGES. RIH W/ PACKI	ER,
3/09/98 - RIH TO LOCATE LEAK. SET RBP AT 45 CASING TO 500 PSI. RIH W/ 4-3/4" BIT. TAG CEM RIH TO 2516'. SPOT 105 SX 'G' CEMENT. PRESS HELD OK. DRILL OUT OF CEMENT AT 2540'. TESPULL RBP AT 4780'. CLEAN OUT TO 6930'. SPOT 2-1/16" TUBING TO 6820', 5-1/2" PACKER SET AT	MENT AT 2123'. DRILL TH SURE CASING TO 500 PSI ST TO 500 PSI, HELD OK. T 1000 GAL. 15% HCL ACF	IRU CEMENT AT 2412'. T I. TAG CEMENT AT 1690' . RIH W/ 5-1/2" SCRAPPE ROSS DAKOTA PERFS. I	EST CASING . DRILL CEM R TO 4500'. ' RIH W/ PROD	TO 500 PSI. SLIGHT LEAK ENT TO 2228'. TEST TO 50 TESTED OK. PULL RBP AT UCTION TUBING AS FOLL	(-OFF. 20 PSI, 4529'.
3/20/98 - HOOK WELL INTO SALES LINE.					
3/23/98 - RIG DOWN, RELEASE RIG.			កាត	ECEIVED	
			ות ב		1
			<i>וו</i> ע	APR - 6 1998	
)		© []	L GON. DIV. DIST. 3	>
	mowledge and belief. TITLE Opera	ating Unit Manager		DATE 4/1/98	
SIGNATURE (Allen Device	111 66 66	.g - : : : : : : : : : : : : : : : : : :			7
TYPE OR PRINT NAME Allen Davis				Telephone No. 325-439	
(This space for State Use) APPROVED BY ORIGINAL SIGNED BY EKNIE	ОЕРИТУ BUSCHTITLE	OIL & GAS INSPECTOR,	DIST. #3	DATE APR 1 3	1998
			7,		