UNITED STATES SUBMIT IN TRIPLICATE OF THE INTERIOR (Other Instructions) on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GFOL	OGICAL.	SURVEY	

16.	Check Appropriate Box To Indicate Nature of Notice, Repo	ort, or Other Data
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
Unit 3	860' FWL Scotion 23 1939 FEL T-31-W, R-14-W	11. SEC., T., R., M., OL BLK, AND SURVEY OR AREA
4. LOCATION OF WELL (I See also space 17 bel At surface	Report location clearly and in accordance with any State requirements *	10. FIELD AND POOL, OR WILDCAT
1 7 15 Security 1	ile Building, Denvor, Colorado 60202	
3. ADDRESS OF OPERATOR	B	9. WELL NO.
	ROBSKI I. W YSI	lia i omnain Tribal 2-2
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
OIL GAS WELL WELL	OTHER	7. UNIT AGREEMENT NAME
(Do not use this	NDRY NOTICES AND REPORTS ON WELLS form for proposals to drill or to deepen or plug back to a different reservoi Use "APPLICATION FOR PERMIT—" for such proposals.)	
		6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT		PULL OR ALTER CASING MULTIPLE COMPLETE		WATER SHUT-OFF REPAIRING WELL FRACTURE TREATMENT ALTERING CASING
SHOOT OR ACIDIZE		ABANDON*	7.7	SHOOTING OR ACIDIZING ABANDONMENT*
REPAIR WELL		CHANGE PLANS		(Other)
(Other)		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

SCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Request approval of the following plans to plug and abandon since oil is no longer producible in paying quantities and no workever possibilities exist:

- 1. . 190' plug w/25 ex coment 3450 to 3640' (T.D.) in 4-3/4" apan hale from 3500' to 3640' and in 5-1/2" 14% casing 3450' to 3500'.
- 2. 100' plug w/25 sx cament from 1700' to 1800' across 5-1/2 tasing cat estimated @ 1756'.
- 100' plug w/34 sx cement in 7-7/8" open hole from 945' to 1045' across top of 3. Mesa Verde formation @ 994'.
- 4. 50' plug W/18 ax cament in top of 8-5/8" 24% surface casing:
- 5. Heavy mud between all plugs.
- 6. Steel marker w/4" pipe 4' above ground level.
- 7. Clean up location.
- 8. Estimate work to be done during September, 1967.



18. I hereby certify that the pregoing is true and correct	
SIGNED Color Signed Owner	DATE AUJ. 28, 1967
(This space for Federal or State office use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE