Form 3167-5 (Jun. 1994)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

PORM AF	PROVED
Budget Bureau	No. 1004-013:

THE PARTICION AND DE		I - 149 - IND - 7652
CHNUBA NULICES WAD U	EPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
and the annual to drill or to	deeden of teentry to a different lage.	voir.
Use "APPLICATION FOR PERMI	IT—" for such proposals	NAVAIO ICID-IL
		7. If Unit or CA, Agreement Designation
SUBMIT IN TRI	PLICATE	
yps of Well		Hoeseshae Gallup UN 8. Well Name and No.
ON Ges Other W. I. W.		Wasseles Callus # 96
the of County		Hoeseshoe Gallup \$ 96
ANTAGE POINT OPERATING	Co. 713-780-1952	3004510.537
Address and Telephone No.	40/2	10. Field and Pool, or Exploratory Area
Address and Telephone No.	x. 77057-9866	Hoeseshoe GAllup
Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
1880 FSL & 340 FEL Sec. 23 T.	31-N R-17-W	
IBBU FOL F 390 PEL Dec. 25 1.		SAN JAUN COUNTY, N. M.
CHECK APPROPRIATE BOX(s) TO I	NDICATE NATURE OF NOTICE, F	REPORT, OR OTHER DATA
CHECK APPHOPHIATE BOX(S) TO T	TYPE OF A	CTION
TYPE OF SUBMISSION	ITFE OF A	
Notice of Intent	Abandonment Recompletion	Change of Plans  New Construction
ET LOUIS A THUM	- 11 32 1000	New Construction  Non-Routine Fracturing
Subsequent Report	Plugging Back	Water Shut-Off
JULT & 1993		Conversion to Injection
Final Abandonment Notice IL CON. D	Altering Casing	Disnoss Water
		(Note: Report results of multiple completion on W
DIST. 3  Describe Proposed or Completed Operations (Clearly state all pertinent and measured and true vertical depths	details and give pertinent dates, including estimated date	of starting any proposed work. If well is directionally dri
Describe Proposed or Completed Operations (Clearly state all pertinent give subsurface locations and measured and true vertical depths as a second se	, 1040	
IT is proposed to Pe A This The proposed procedure is To is 163' Above Top Perfs: W. From 800' To 138'. Perforate Around Bradenhead & Brin 512" CSG. & 858" CSG. W/ Ceme	s well do To Failure  spot cement from 1113  o.C. 2 hrs. Tag Plug.  e Csg @ 138 Establis  G cmt. To Surface.	SPOT SECOND Plug
IT is proposed to P&A This The proposed procedure is To is 163' Above Top Perfs: W. From 800' To 138'. Perforate Around Bradenhead & Brin 51/2" CSG. & 85/8" CSG. W/ Ceme  4. I hereby certify that the foregoing is true and correct Signed Coff Chausing	S Well do To FAITURE  Spot Cement From III: O.C. 2 hrs. TAG Plug. e CSG @ 138 ESTAblis G CMT. To Surface. ENT TO SURFACE.	Spot second Plug Spot second Plug RECEIVED This FIRSTON, NM
IT is proposed to P&A This The proposed procedure is To is 163' Above Top Perfs: W. From 800' To 138'. Perforate Around Bradenhead & Brin 51/2" CSG. & 85/8" CSG. W/ Ceme 4. I horsely conting that the foregoing is true and correct	S WELL do To FAITURE  Spot Cement From III: O.C. 2 hrs. TAG Plug. E CSG @ 138 ESTAblis G CMT. To Surface.  ENT TO SURFACE.  TITLE CONSULTANT OUSITE TE	Spot second Plug Spot second Plug RECEIVED This FIRSTON, NM
IT is proposed to P&A This The proposed procedure is To is 163' Above Top Perfs: W. From 800' To 138'. Perforate Around Bradenhead & Brin 51/2" CSG. & 85/8" CSG. W/ Ceme  4. I hereby carrier that the foregoing is true and correct Signor Control or State office uses)  (This spece for Federal or State office uses)	S Well do To FAITURE  Spot Cement From III: O.C. 2 hrs. TAG Plug. e CsG @ 138 Establis G Cmt. To Surface.  ENT To Surface.	SPOT SECOND Plug  She Circulation  This FIRST GOTH  Ch. LTD DIE 7-6-93  APPOR OVED
IT is proposed to P&A This The proposed procedure is To is 163' Above Top Perfs: W. From 800' To 138'. Perforate Around Bradenhead & Brin 51/2" CSG. & 85/8" CSG. w/ Ceme  4. I hereby certify that the foregoing is true and correct Signor Control or State office used	S WELL do To FAITURE  Spot Cement From III: O.C. 2 hrs. TAG Plug. E CSG @ 138 ESTAblis G CMT. To Surface.  ENT TO SURFACE.  TITLE CONSULTANT OUSITE TE	Spot second Plug Spot second Plug RECEIVED This FIRST GOTH BLM This FIRST GOTH, NM  Ch. LTD Done 7-6-93

## UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 96 Horseshoe Gallap Unit.

## CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Mark le/ly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

Our records indicate that the 8% Surface casing was set 2' 126'. Perforate 2176' (50' below surface casing) and circulate cement to the surface.

Office Hours: 7:45 a.m. to 4:30 p.m.