


(SUBMIT IN TRIPLICATE)

Land Office **Santa Fe, N.M.**

Lease No. **NM 021126**

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

OCT 17 1953

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Notice of intention to alter tubing X	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 14, _____, 19**53**

Well No. **1-20** is located **925'** ft. from **[N]** line and **1020** ft. from **[E]** line of sec. **20**

SW NE NE (¼ Sec. and Sec. No.)	31N (Twp.)	12W (Range)	N.M.P.M. (Meridian)
West Blanco (Field)	San Juan (County or Subdivision)	New Mexico (State or Territory)	

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To increase gas production by pulling 2" tubing and running 1½" tubing with gas lift valves at pre-determined intervals - will then intermittent fluids through the tubing and produce gas through the annulus and increase production.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Ohio Oil Company**

Address **P.O. Box 120, Casper, Wyoming**

By **W. A. Pae**

Title **Production Foreman**
P.O. Box 946, Durango, Colo.