orm 3160-5		FORM APPROVEDY
June 1990)		Budget Bureau No. 1004-0135
		Expires: March 31, 1993
UNITED ST		5. Lease Designation and Serial No.
DEPARTMENT OF		14-20-603-2022
BUREAU OF LAND	MANAGEMENT	6. If Indian, Allottee or Tribe Name
SUNDRY NOTICES AND I	REPORTS ON WELLS	Navajo
Do not use this form for proposals to drill or to	deepen or reentry to a different reservoir,	7. If Unit or CA. Agreement Designation
Use "APPLICATION FOR PER		S
SUBMIT IN TRIPLICA		Horseshoe Gallup Unit
. Type of Well		8. Well Name and No.
Oil Well Gas Well	X Other WIW	HGU #87
Name of Operator .		9. API Well No.
2. Name of Operator, Playa Minerals & Energy, Inc. c/o Playa Minerals & Energy, Inc.		30-045-10648
Address and Telephone No.	nerals & Ellergy, Inc.	10. Field and Pool, or Exploratory Area
•	77060 (201) 021 2000	1
650 N. Sam Houston Pkwy. E. Houston, Tx		Horseshoe Gallup Unit
Location of Well (Footage, Sec., T., R., M., or Survey I		11. County or Parish, State
909' FNL, 1914' FEL, Sec. 24, T31N, R17V		San Juan County, NM
. CHECK APPROPRIATE BOX(s) TO INDICATI		R DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
	X Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
X Subsequent Report	Casing Repair	Water Shut-Off
		Conversion to Injection
		recurrence to injection
	Altering Casing	Dioposa Wotor
Final Abandonment Notice	Other	Dispose Water Note: Report results of multiple completion on Well
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured	Other	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ny proposed work. If well is
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a)	Other	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) by proposed work. If well is nent to this work.) *
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state aldirectionally drilled, give subsurface locations and measured	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones pertinents.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) by proposed work. If well is nent to this work.)*
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones pertinents.	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) by proposed work. If well is nent to this work.) *
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured See attached report.	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones pertinents.	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) by proposed work. If well is nent to this work.)* DEC 2
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state aldirectionally drilled, give subsurface locations and measured See attached report. 4. I hereby certify that the foregoing is true and correct	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones perti	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) BEC 2 DIFL Completion or Recompletion Report and Log form.)
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured See attached report. 4. I hereby certify that the foregoing is true and correct	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones pertinents.	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) by proposed work. If well is nent to this work.)* DEC 2
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured See attached report. 4. I hereby certify that the foregoing is true and correct	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones perti	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) BEC 2 DIFL Completion or Recompletion Report and Log form.)
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured See attached report. 4. I hereby certify that the foregoing is true and correct Signed Mark L. Ehrman	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones perti	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) BEC 2 DIFL Completion or Recompletion Report and Log form.)
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured See attached report. 4. I hereby certify that the foregoing is true and correct Signed Mark L. Ehrman (This space for Federal or State office use)	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones perti	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) BEC 2
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured See attached report. 4. I hereby certify that the foregoing is true and correct Signed Mark L. Ehrman (This space for Federal or State office use) Approved by	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones pertinent dates. Title Regulatory Compliance	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) by proposed work. If well is ment to this work.)* DEC 2 Date 12/10/99
Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state a directionally drilled, give subsurface locations and measured See attached report. 4. I hereby certify that the foregoing is true and correct Signed Mark L. Ehrman	Other I pertinent dates, including estimated date of starting ar and true vertical depths for all markers and zones pertinent dates. Title Regulatory Compliance	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) By proposed work. If well is ment to this work.)* DEC 2 DIFF. (1995)

*See Instruction on Reverse Side

CCEPTED FOR RECORD

DEC 2 1 1999

FARMING, ON TILLE OFFICE BY________



Key Energy Services, Inc.

Four Corners Division P.O. Box 900 5651 US Highway 64 Farmington, NM 87499

Phone: 505-327-4935 Fax: 505-327-4962

ED ED 13 33 1: 44

And the second s

P&A OPERATION CEMENT SERVICE REPORT

WELL NAME: HORSESHOE GALLUP UNIT #87

TOTAL PLUGS SET: 2

DATE STARTED: 11-23-98

TOTAL SACKS USED: 107 sx.

DATE COMPLETED: 12-01-98

BLM WITNESS: J. SANCHEZ OPERATOR WITNESS: N/A

MOL AND RU. RU RELIEF LINE AND BLEED DOWN WELL. CIRCULATED TUBING CLEAND WITH WATER. ND WELLHEAD AND NU BOP, WORKED ON TUBGING SLIPS FOR 5 HRS. STRAPPED OUT WITH 1207' OF 2 3/8" TBG, NO PAK\CKER ON BOTTOM. ESTABLISHED INJECTION RATE INTO PERFORATIONS WITH WATER AT 1 BPM WITH 750 PSI.

PLUG #1 (1004' - 1260'),

PU AND RIH WITH 5 ½" RETAINER AND SET AT 1273'. MIXED 42 SX CL. B CEMENT PLUG, PLACING 12 SX BELOW AND 31 SX ABOVE RETAINER. POH.

PLUG #2 (0' - 165'),

RIH WITH WIRELINE AND PERFORATED SQUEEZE HOLES AT 165'. CIRCULATE HOLE CLEAN WITH WATER. MIXED 56 SX CL. B CEMENT PLUG TO CIRCULATE GOOD CEMENT TO SURFACE. BRADON HEAD FLOWING SLOWLY, SHUT IN AND WOC. CUT OFF WELLHEAD AND TOPPED OFF CASINGS WITH 8 SX CL. B CEMENT. RD RIG AND MOL.

NATHAN E. CRAWFORD. P&A SUPERVISOR