

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-604-1948-A

6. INDIAN, ALLOTTEE, OR TRIBE NAME

Navajo and Ute

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Horseshoe Gallup Unit

9. WELL NO.

276

10. FIELD AND POOL, OR WILDCAT

Many Rocks-Gallup

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

21, 31N, 16W, NMPM

12. COUNTY OR PARISH 13. STATE

San Juan New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

Box 810, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' from North and West section lines

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5729' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has reached its economic limit and has been shut-in for most of 1967. Since there are no prospects of returning this well to a commercial producer, we propose to plug well as follows:

Spot 10 sack cement plug over perforations 1640' to 1643' and 1774' to 1781'. Fill hole with mud and pull tubing. Remove casing and tubing heads and set marker in 10 sack cement surface plug. Clean up location.



RECEIVED

NOV 17 1967

U. S. GEOLOGICAL SURVEY
FARMINGTON, N.M.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

District Superintendent

DATE

11/16/67

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTES AND REPORTS ON WELLS

THIS FORM IS DESIGNED FOR THE PRESENTATION OF SUNDRY NOTES AND REPORTS ON WELLS. IT IS TO BE FILLED OUT BY THE OPERATOR OF THE WELL, OR BY SOME OTHER PERSON HAVING KNOWLEDGE OF THE WELL, AND IS TO BE SUBMITTED TO THE GEOLOGICAL SURVEY FOR THE RECORD.

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local, State or Federal office for specific instructions.

Item 7: Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1981-3-484529
507-951

