Form 3160 3 (June 1990

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

PORM APPROVED	
Budget Bureau No. 1004-013:	9
Expires: March 11, 1991	

BUREAU OF LAND MANAGEMENT	5. Lease Designation and Serial No.
	14-20-603-2022
SUNDRY NOTICES AND REPORTS ON WELLS	6. If Indian, Allonse or Tribe Name
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	721
Use "APPLICATION FOR PERMIT—" for such proposals	NAVAio
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well	<u></u>
OH Gas Well Other	HORSESHOR GALLUP UNI
2. Name of Operator	** *** **** ***** ***** *****
VANTAGE POINT OPERATING, Co (713) 780-1952 3. Address and Telephone No.	Horseshoe Gallup # 7
	10. Field and Pool, or Exploratory Area
2401 FOUNTAIN DR. HOUSTON, TX 77057-4862 4. Location of Well (Poolage, Sec., T., R., M., or Survey Description)	Hoeseshoe Gallup
2100 100 1 100 1	11. County or Parish, State
2155 FSL & 477 FEL Sec. 14 T-31-N R-17-W	
·	SAN JAUN COUNTY N.M.
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT	RT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent	Change of Plans
_ Recompletion	New Construction
Subsequent Report	Non-Routine Fracturing
JUL1 2 1993, Casing Repair	☐ Water Shut-Off
L Final Abandonment Notice Ahartae Casine	Conversion to Injection
OIL CON. DIV.)	Dispose Water
DIST. 3	(Note: Report results of multiple completion on W Completion or Recompletion Report and Log for
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally dri
856" @ \$6' PBTD @ 1365' Perforations! 1334'-1352'	
IT is proposed to P&A This Well due to Failure to PA	SS M.T.T.
The Proposed Decreduce is To some of	
The proposed procedure is To Spot Cement From 1365 PBTD	To 120' 3
which is 134' Above Top Perfs. W.O.C. Zhes. Tag Plug. Set	J. 7. J
Plug From 1700 + 183 T	Second
10 136. PERFORATE CSC @ 136' ESTABLISH C	iRCUTATION BC
HROUND BRAdenhead & Pump CMT To	P 3
both 51/2: CSG & OSL" The Surface From 136. The	is fills = Th
cos to surface w/ coment.	2. S. D
Plug From 1200' To 136. Perforate Coc @ 136' Establish C Around Bradenhead & Pump CmT. To surface From 136. The both 51/2" CSG & 856" CSG To surface w/ Cement.	<u> </u>
SEE ATTACHED FOR	-
CONDITIONS OF APPROVAL	
COMPLICATION	
14. I hereby certify that the foggeoing is true and express	

Signed Conditions of approval, if any:

14. I hereby certify that the foregoing is true and correct

Signed Conditions of approval, if any:

Title Conditions of approval, if any:

APPROVED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Limits and self-ball on the self-ball of the Limits and the self-ball of the self-bal

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 76 Horseshoe Gallup Unit

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907

- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 7:45 a.m. to 4:30 p.m.