

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
SEP 16 1991
Bureau of Land Management
Durango, Colorado

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other W: 505-325-6771 or
Telephone: H: 505-327-7634

2. Name of Operator
W.M. Gallaway

3. Address and Telephone No.
3005 Northridge, Suite I, Farmington, N.M. 87401

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec. 15, T31N, R15W N.M.P.M.
1895' FNL, 700' FWL

Lease Designation and Serial No.
14-20-151-46

6. If Indian, Allottee or Tribe Name
Ute Mountain Indian

7. If Unit or CA, Agreement Designation
Ute Indian A

8. Well Name and No.
7

9. API Well No.
300458700100S1

10. Field and Pool, or Exploratory Area
Verde Gallup

11. County or Parish, State
San Juan Co., N.M.

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Work
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other Work was done on
July 10, 11, 12, 1991

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rolled hole with 9.3# Mud 45 Viscosity
2. Spotted 25 15.2# cement through 2-3/8" tubing in 2 1/8" open hole, pulled tubing up hole, let set 4 hours. Tagged cement top in 4-1/2" casing at 1780'.
3. Spotted 15 sacks of 15.2# cement inside of 4-1/2" casing from 1650' to 1550'
4. Perforated 4-1/2" casing at 600' squeezed perforation with 30 sacks of 15.2# cement, plug from 650' to 550' inside and outside of 4-1/2" casing.
5. Perforated 4-1/2" casing at 155'. Circulated down 2-3/8" tbg out 7-5/8" Bradenhead for 10 min. Circulated hole with 20 sks 15.2# cement. Good return throughout.
6. Spotted 5 sacks in top of 4-12/" casing
7. Cleaned location and erect dry hole marker.
8. Surface restoration will be handled as specified by surface management agency

14. I hereby certify that the foregoing is true and correct

Signed W.M. Gallaway

Title Operator

Date 8-01-91

(This space for Federal or State office use)

Approved by (S) Kent Hoffman
Conditions of approval, if any:

Title ACTING AREA MANAGER

Date NOV 16 1991

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side