

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

OCT 5 1992

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Bureau of Land Management

SUNDRY NOTICES AND REPORTS ON WELLS Durango, Colorado

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

20-604-82

6. If Indian, Allottee or Tribe Name

UTE MOUNTAIN INDIAN

7. If Unit or CA, Agreement Designation

UTE INDIAN E

8. Well Name and No.

7

9. API Well No.

300458700100S1

10. Field and Pool, or Exploratory Area

VERDE GALLUP

11. County or Parish, State

SAN JUAN CO, N.M.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

W.M. GALLAWAY

3. Address and Telephone No.

3005 NORTHRIDGE, SUITE I, FARMINGTON, NM (505) 325-6771

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

780' FNL AND 2110' FWL

SEC. 17, T31N, R14W

0Y327-7634

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Roll hole with 9.2#, Mud 40 to 45 Viscosity

2. Spot Cement across Gallup

Perforations in 5½" casing from 2430' to 2560' and continue up 5½" casing to 2380'
30 sacks

3. Perforate Mesa Verde @ 1190' and cement inside and outside from 1140' to 1240' with 25 sacks

4. Perforate 5½" casing 10' below bottom of surface pipe @ 116' and circulate to surface 25 sacks estimate

5. Top Plug 50' inside 5½" casing 10 sacks

6. Erect Dry Hole Marker

7. Clean location and seed to specifications

14. I hereby certify that the foregoing is true and correct

Signed *W.M. Gallaway*

Title Operator

Date 10-1-92

(This space for Federal or State office use)

(s) Kent Hoffman

ACTING

Title AREA MANAGER

Date OCT 8 1992

Approved by
Conditions of approval, if any:

W. M. Gallaway
Ute Mountain Ute Lease 14-20-604-82
Ute Indian E No. 7 1 Well
NE NW Sec. 14, T. 31 N., R. 14 W.
San Juan County, New Mexico

Conditions of Approval - Downhole Abandonment

1. Secure prior approval before changing the proposed plugging program.
2. Contact this office at (303) 247-4082, 48 hours prior to commencing abandonment operations.
3. Within 30 days after plugging work is completed, file 3 copies of Subsequent Report of Abandonment on Form 3160-5. This report should include types of plugs, depth and thickness of all plugs, and date that well was plugged. Seeding requirements will be provided by BIA at a later date.
4. Cement behind 5 1/2" casing must be circulated from at least 50 feet below surface casing shoe to surface.
5. Tag Mesa Verde plug.