Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM Byager Bun	APPR	OVED
Bydger Bun	eme No.	1004-013
/ Expires:	March	31, 1993

RURFALLOS	FIAND MANACEMENT	Experts: March 31, 793
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No. 14-20-603-2034
		6. If Indian, Allottee or Tribe Name
not use this form for proposals to	drill or to deepen or reentry to a different reservoir.	
USE "APPLICATION F	OR PERMIT—" for such proposals	Navajo Tribal
CUDA	IT IN TOIGH A TTE	7. If Unit or CA, Agreement Designa
	IT IN TRIPLICATE HOLE 1 9 1600	
pe of Well	1: W NOV 0 1939	
Weil Weil Other		8. Well Name and No.
me of Operator	(0) IL GUING DING	Navajo T. I. "F" #/
Hart Oil and Gas Inc.		9. API Well No.
Idress and Telephone No.		30045 1095 5005
5200 Villa View Dr. #13A - Farming cation of Well (Footage, Sec., T., R., M., or Survey	gton, N. M. 87402 (505) 326-1163	10. Field and Pool, or Exploratory Are
	Description)	Horseshoe Gallup
Section 0 - 31N 17W		11. County or Parish, State
80 FNL & 660 FEL		San Juan, N. M.
CHECK APPROPRIATE BOX	((s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Паши
	Recompletion	Change of Plans New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
—X 2000-1-00	Casing Repair	Water Shut-Off
Final Abandonment Notice		Conversion to Injection
Final Abandonment Notice	Alterine Casine	Conversion to Injection Dispose Water
acribe Proposed or Completed Operations (Clearly state give subsurface locations and measured and true vert The well had a hole in the tubing.	Altering Casing Returned to production all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work.)* We installed new tubing and a new pump. We a	Dispose Water (Note: Report results of multiple completion of Completion or Recompletion Report and Log gany proposed work. If well is directionally
cribe Proposed or Completed Operations (Clearly state give subsurface locations and measured and true vert The well had a hole in the tubing. Replaced any bad rods and rod be The well was returned to production. My name is Andrew B. Saied and I The new address is: 5200 Villa V	Altering Casing Returned to production all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work.)* We installed new tubing and a new pump. We access that were not spray metal coated. ion on 9-24-99 i purchased Hart Oil and Gas Inc. effective 9/1/99 iew Drive #13A New Mexico 87402	Dispose Water (Note: Report results of multiple completion of Recompletion Report and Lag g any proposed work. If well is directionally
The well had a hole in the tubing. Replaced any bad rods and rod be. The well was returned to producti My name is Andrew B. Saied and if The new address is: 5200 Villa V. Farmington, Phone: 505-2 is space for Pederal or State office use)	Altering Casing Returned to production all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work.)* We installed new tuibing and a new pump. We access that were not spray metal coated. In purchased Hart Oil and Gas Inc. effective 9/1/99 Title PRESIDENT Title PRESIDENT	Dispose Water (Note: Report mode of multiple completion of Recompletion Report and Lag g any proposed work. If well is directionally
The well had a hole in the tubing. Replaced any bad rods and rod be The well was returned to producti My name is Andrew B. Saied and i The new address is: 5200 Villa V Farmington, Phone: 505-	Altering Casing Returned to production all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work.)* We installed new tubing and a new pump. We appeared that were not spray metal coated. In on 9 - 24 - 99 I purchased Hart Oil and Gas Inc. effective 9/1/99 The We make the coated of the	Dispose Water (Note: Report mode of multiple completion of Recompletion Report and Lag g any proposed work. If well is directionally

*See Instruction on Reverse Side



