

FORMATION RECORD—Continued

[illegible]

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was "sidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

4-29-58 T.D. 6195. CONTD 6158. Water Trac. Point Lookout part. Int. 5864-5904; 6050-6072; 6082-6094; 6108-6146 w/ 1 shot/ft; 5994-6014; 6038-6051 w/2 shot/ft w/87,000 gal. water, 90,000 gal. B.H.P. Home, M.P. 23507, T.P. 1350-1500-1800-2200#. I.R. 67 B.P.M. Flush 10,000 gal. Drilled 5 sets of 15 balls.