X

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office San to				
Loaso	No	22		
Unit	Back	1/2	Jes.	17
	Sact.		7	

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	1 11
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHECK MA	RK NATURE OF REPORT, NOTICE, OR OTHER DATA)
(1151212121211311131	
	from $\begin{bmatrix} N \\ M \end{bmatrix}$ line and 990 ft. from $\begin{bmatrix} E \\ M \end{bmatrix}$ line of sec.
(14 Sec. and Sec. No.) (Twp.)	(Range) (Meridian)
Wildred Dogwood / Fan Jran	nty or Subdivision) (State or Territory)
(Field) (Cour	nty or Subdivision) (State or Territory)
he elevation of the derrick floor above sea	level is ft.
State names of and expected depths to objective sands; show	AILS OF WORK sizes, weights, and lengths of proposed casings; indicate mudding jobs, ceall other important proposed work)
Hese Verde will be drilled with Rotary tools will be used to TD. Propose Casing: Set 10-3/4" easing at 150'	y 5000' using and. Set casing at top of gas and eleaned out with gas after shot. and coment with approximately 200 sax. coment with approximately 200 sax.
Hesa Verie will be drilled with Rotary tools will be used to TD. Propose Casing: Set 10-3/4" easing at 150' Set 7" casing at top of pay Lecation Plat attached. I understand that this plan of work must receive approval	gas and ele-ned out with gas after shot. and coment with approximately 200 sax. coment with approximately 200 sax.
Hese Verie will be drilled with Rotary tools will be used to TD. Propose Casing: Set 10-3/4" easing at 150' Set 7" casing at top of pay lecation Plat attached. I understand that this plan of work must receive approval Company Phillips Patroloum Company	gas and ele-ned out with gas after shot. and coment with approximately 200 sax. coment with approximately 200 sax.
Mesa Verde will be drilled with Rotary tools will be used to TD. Propose Casing: Set 10-3/4" easing at 150' Set 7" casing at top of pay Location Plat attached.	gas and ele-ned out with gas after shot. and coment with approximately 200 sax. coment with approximately 200 sax.
Hese Verie will be drilled with Rotary tools will be used to TD. Propose Casing: Set 10-3/4" casing at 150' Set 7" casing at top of pay lecation Plat attached. I understand that this plan of work must receive approval company Phillips Patroloum Company	gas and ele-ned out with gas after shot. and coment with approximately 200 sax. coment with approximately 200 sax.