

FOLD MARK	casing	where set			
	10 3/4 7	227 5113	200 425	Howco Howco	

PLUGS AND ADAPTERS

Heaving plug—Material Length Depth set
 Adapters—Material Size

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
3 1/2 x 5 x 30'	Matial	ENG	1700	12-16-53	5193-5737	5737

TOOLS USED

Rotary tools were used from feet to feet, and from feet to feet
 Cable tools were used from Surface feet to 5737 feet, and from feet to feet

DATES

....., 19..... Put to producing, 19.....
 The production for the first 24 hours was barrels of fluid of which% was oil;%
 emulsion;% water; and% sediment. Gravity, °Bé.
 If gas well, cu. ft. per 24 hours Gallons gasoline per 1,000 cu. ft. of gas
 Rock pressure, lbs. per sq. in.

EMPLOYEES

....., Driller , Driller
 Jack Morgan, Tool Pusher , Driller Wayne Woodall , Driller
 Dale Jackson

FORMATION RECORD/Becker

FROM—	TO—	TOTAL FEET	FORMATION
Surface	2732	2732	Tertiary Sands & Shales
2732	3249	517	Fruitland
3249	3350	101	Pictured Cliffs
3350	4948	1593	Lewis
4948	5230	282	Cliff House
5230	5547	317	Nenefee
5547	5695	148	Point Lookout
5695	5737	42	Wancos
	5737		