

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease		
State	Fed	For <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.		

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Aztec Oil & Gas Company		8. Farm or Lease Name Waller
3. Address of Operator P. O. Drawer 570, Farmington, New Mexico		9. Well No. #1
4. Location of Well UNIT LETTER <u>M</u> <u>890</u> FEET FROM THE <u>South</u> LINE AND <u>790</u> FEET FROM THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>32 North</u> RANGE <u>11 West</u> NMPM.		10. Field and Pool, or Wildcat Blanco Mesaverde
15. Elevation (Show whether DF, RT, GR, etc.) 6408 GR		12. County San Juan


Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSE TO:

Squeeze off existing Mesaverde perforations.  
Set whipstock approximately 4700'.  
Re-drill Mesaverde formation.  
Run 4-1/2" casing, perforate and sand/water frac Mesaverde.  
Run 1-1/2" tubing.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe C. Ramsey TITLE District Superintendent DATE April 26, 1973

APPROVED BY George C. Ramsey TITLE SUPERVISOR DIST. #3 DATE APR 26 1973

CONDITIONS OF APPROVAL, IF ANY: