

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

## Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator

**BURLINGTON  
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1490' FSL, 1800' FWL, Sec. 11, T-32-N, R-10-W, NMPM

Lease Number

SF-079143

6. If Indian, All. or  
Tribe Name

Unit Agreement Name

San Juan 32-9 Unit

Well Name & Number

San Juan 32-9 Unit #55

9. API Well No.

30-045-11494

10. Field and Pool

Blanco Mesaverde

11. County and State

San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	

13. Describe Proposed or Completed Operations

10-12-98 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg. TIH w/5 1/2" csg gauge ring to 5280'. TOOH. TIH w/5 1/2" CIBP, set @ 5234'. TOOH. SDON.

10-13-98 PT csg to 500 psi/15 min., OK. Plug #1 w/47 sx Class "B" neat cmt. Displace @ 5234' to 4819'. Plug #2 w/50 sx Class "B" neat cmt. Displace @ 3655' to 3213'. TOOH. TIH w/wireline. Perforate 3 holes @ 3010'. Circ hole clean. SDON.

10-14-98 ND BOP. Welded 5 1/2" csg collar on csg stub. TIH w/collar splitter & split csg collar @ 2994'. Wrap primer cord around csg, free csg slips. TOOH w/5 1/2" csg. SDON.

10-15-98 TIH. PT csg to 500 psi/15 mins., OK. Plug #3 w/47 sx Class "B" neat cmt. Displaced @ 3052' to 2830'. TOOH. TIH w/wireline. Perforate 3 holes @ 1905'. TOOH w/wireline. TIH, set cmt retainer @ 1853'. Plug #4 w/85 sx Class "B" neat cmt, squeezed 56 sx below cmt retainer. Displaced @ 1853' to 1728'. TOOH. TIH w/wireline. Perforate 3 holes @ 220'. TOOH w/wireline. Plug #5 w/113 sx Class "B" neat cmt. 1 bbl cmt returned. ND BOP. Dig out and remove WH. Marker installed. RD. Rig released.

14. I hereby certify that the foregoing is true and correct.

Signed Regina Shadwell Title Regulatory Administrator Date 10/21/98  
vkh

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date AL

CONDITION OF APPROVAL, if any: