

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. 14-30-0103-7116	
2. NAME OF OPERATOR Standard Oil Company of Texas A Division of Chevron Oil Co.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribal	
3. ADDRESS OF OPERATOR 3610 Avenue B, Daviess, Texas		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit 7, 1980' sal and 1980' sal, Sec. 35, T14N, R16W		8. FARM OR LEASE NAME Navajo Tribal 21	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) DF 3026		10. FIELD AND POOL, OR WILDCAT Refined	
		11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA Sec. 35, T14N, R16W	
		12. COUNTY OR PARISH San Juan	
		13. STATE New Mex.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☒ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been plugged and abandoned in the following manner:

2/3/66 Move in abandonment tools
2/4/66 Mix and spot 50 ex plug across part. 6672-6772
Attempt to squeeze - no press.
2/3/66 Test plug - no press.
2/7/66 Made 4 dump bailer runs. Spotted 8 ex cement across part.
2/8/66 Check run w/bailer, indicated no fill up.
2/8/66 Dump 55 gal. (Pen gravel & sand in well)
2/9/66 Dump 12 ex cement w/dump bailer - 6697 to 6612
2/10/66 Load hole w/114/gal mud and press. test to 1000 psi.
2/10/66 Cut 5 1/2" casing off at 3746' - recovered same.
2/28/66 Killed water flow w/more mud thru tubing from 3050',
Spotted 7% ex plug 2350 to 2550
Spotted 3% ex plug 1150 to 1250.
3/1/66 Weld plate over surf. casing, install P & A markers.



18. I hereby certify that the foregoing is the And Dagen

SIGNED

TITLE

Agent

DATE

4/1/66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

S. GEOLOGICAL SURVEY

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for special instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.