

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-00-0100-7136

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Savajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Savajo Tribal 12-36

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 36, T21N, R18W

12. COUNTY OR PARISH

San Juan

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. NAME OF OPERATOR Standard Oil Co. of Texas A Division of Chevron Oil Company	
3. ADDRESS OF OPERATOR 3610 Avenue B, Snyder, Texas	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit 2, 1980' fol 660' fol Sec. 36, T21N, R18W	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) DF 5130

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐


SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☒ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been plugged and abandoned in the following manner:

1/7/66 Move in abandonment tools - mixed mud.
1/8/66 Circulate hole w/11/2 gal mud
1/9/66 Spot 15 cu plug across perf. 6248 to 6936
Squeeze w/2000 psi. Pull up and reverse out 5 cu.
1/16/66 Attempt to recover casing from 1298
Unable to recover, shot cong. free at 1297' - RECOVERED SAME
Spot 90 cu plug across stub
1/17/66 Remove wellhead, weld on plate over surface pipe.
Install P & A Marker



18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by T. A. Dugan TITLE AgentDATE 4/1/66

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.