

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Consolidated Oil & Gas Inc.	8. Farm or Lease Name Kline
3. Address of Operator P.O. Box 2038, Farmington, New Mexico	9. Well No. 1-16
4. Location of Well UNIT LETTER G , 1850 FEET FROM THE North LINE AND 1550 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 31 North RANGE 13 West NMPM. Mesavore & Dakota	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 5715 G.L.	12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move in completion rig. Rig up and pull 1" and 1 1/2" tubing.
Rig up and run Mc Collough corrosion leg. Locate holes in the casing
and set plug and squeeze with 175 sacks. W.O.C. and pressure up, and
resqueeze if necessary. Rerun 1" and 1 1/2" tubing.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Clyde Phillips TITLE Production Foreman DATE 4-20-65

APPROVED BY Charles E. Arnold TITLE APR 21 1965 DATE Supervisor Dist. # 3

CONDITIONS OF APPROVAL, IF ANY: