16.

UNITED STATES SUBMIT IN TRIPLICATE. DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side) UNITED STATES

Form approved. Budget Bureau No. 42-R1424. 5. ZEASE DESIGNATION AND SERIAL NO.

	GEOLOGICAL SURVEY	/4-20-104-122
	PRY NOTICES AND REPORTS ON WELD orm for proposals to drill or to deepen or plug back to a diffuse "APPLICATION FOR PERMIT—" for such proposals.)	· · · · · · · · · · · · · · · · · · ·
OIL GAS WELL WELL	OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	ROWIET L. ROMS	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR	/ Life Building, Dinver, Coloredo 83	9. WELL NO.
	ort location clearly and in accordance with any State require	
Unit N	330' FSL Section 23 1980' FWI. T+31-N, R-14	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	5484' K.B.	lan Juan - May 1. m

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of mu Completion or Recompletion F	REPAIRING WELL ALTERING CASING ABANDONMENT* Itiple completion on Well Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Request approvel of the following plans to plug and abandon since oil is no longer productible in paying quantities and no workover possibilities exist:

- 156' plug w/20 sx cement 4640' to 4796' (T.D.) in 4-1/2' J.D. 11# liner from 4670' to 4786' and in 5-1/2" 14# casing from 4640' to 4671'.
- 100' plug w/25 sx cement from 2730' to 2830' across 5-1/2" casing out 2. satimated 7 2730'.
- 100' plug wy 34 sx cement in 7-7/6" open hole from 2135' to 2235' across top 3. of Nesa Verde formation @ 2186'.
- 50' plug w/18 sx cement in top of 8-5/8" 24# surface casing. 4.
- 5. Heavy mud between all plugs.
- Steel marker w/4" pipe 4' above ground level. 6.
- 7. Clean up location.
- Estimate work to be done during September, 1967.



SIGNED WINGS	DATE Aug. 29, 1967
(This space for Federal or State office use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE