Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROV E D
Budget Bureau No. 1004-0135
Expires: March 31, 1993

-					_
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.				5. Lease Designation and Serial No.	
				SF-0780	97
Use "/	APPLICATION FOR PERMIT - " for such	proposals	an En	8. If Indian, Allottee or Tribe Name	
			100		
		i	JAN 1	7. A Unit of EA, Agreement Designation	
				100g 🖰	
1. Type of Well Oil Gas		(0	ML (com		
Well Wall Other				8. West Name and No.	#1
2. Name of Operator AMOCO PRODUCTION COM	IDANV	Attention: Gail M. Jefferson	ોહોઉ	P. API Well No.	#1
3. Address and Telephone No.	IFANI	Gail W. Jellerson		4	200
P.O. BOX 800 DENVER, COI	I ORADO 80201	(303) 830-	6157	30045133	200
4. Location of Well (Footage, Sec., T., R., M., or Survey Description				Blanco Mesaverde/	Basin Dakota
4. Location of west (Fuorege, Sec., 1., n., m., or Solvey Description				11. County or Parish, State	
990' FNL 990' F	EL Sec. 28 T	31N R 11W	UNIT A	0441 11144	NEWARYIOO
				SAN JUAN	NEW MEXICO
12. CHECK APPROPRIA	ATE BOX(s) TO INDIC	ATE NATURE OF	NOTICE, REF	ORT, OR OTHER DA	TA
TYPE OF SUBMISSION			TYPE OF ACTION		_
					_
Notice of Intent		Abandonment		Change of Plans	
Notice of Intent		Recompletion Plugging Back	H	New Construction	
Subsequent Report		Casing Repair	H	Non-Routine Fracturing Water Shut-Off	
		Altering Casing		Conversion to Injection	
Final Abandonment Notice		Other Downhole Commingle		Dispose Water	
			(Note: Heport re	sults of multiple completion on Well Completion or	Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all p	pertinent details, and give pertinent dates, including es	timated date of starting any proposed wor	k . If well is directionally drilled, (give subsurface locations and measured	and true vertical depths for all
markers and zones pertinent to this work.)*					
Amoco Production Compan	y requests permission to de	ownhole commingle t	nis well per the a	ttached procedures.	
If you have any technical que concerns.	uestions please contact Dav	ve Koskella at (303) 8	30-4377 or Gail .	Jefferson for any adminis	trative
_ =					
1: 57					
÷ ş					
$\frac{1}{2}$					
المراجع					
3 DEC (
2 5					
•					
14. I hereby certify that the foolgoing is true and correct					
12:0911	Heisen		Cr Admin Ctoff	Anat	12-17-1998
Signed Xall .	yerson -	Title	Sr. Admin. Staff	ASSI. Date	12:17:1330
(This space for Federal or State office use)	' <i>U</i>				
	ree of a contract was a second				1/12/99
Approved by Conditions of approval, if any:	The second second	Title		Date	71-77
Constitute at approves, it stily.					
Title 18 U.S.C. Section 1001, makes it a crime for any person known	ege to Internation of a willfully to make to any department or age	ncy of the United States any false, ficticion	us, or fraudulent statements or re	presentations as to any matter within its jurisdicti	on,



Heaton LS #1 TD = 7150' PBTD = 7080' Page 2 of 2

- 1. Check anchors. MIRUSU.
- 2. Check and record tubing, casing and bradenhead pressures.
- 3. Blow down wellhead, kill if necessary.
- 4. Nipple down wellhead, nipple up and pressure test BOP.
- 5. TOH with 1.25" tubing and 1.50" tubing.
- 6. Drill out Model D packer at 6520'.
- 7. TOH with Model D packer.
- 8. TIH with 2 3/8" tubing with SN on bottom and tag fill.
- 9. If fill is above 7060', clean-out to PBTD. Otherwise, land tubing at 7025'.
- 10. Put well back on production.

