Form 3160-5 (Jur.e 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

| BUREAU OF LAND MANAGEMENT | | Expires: March 31, 1993 |
|---|---|---|
| Do not use this form for propo | Sals to drill or to deepen or reentry to a different reservoir. TION FOR PERMIT - " for such proposals | 6. Lease Designation and Serial No. SF-078095 6. If Indian, Allottee or Tribe Name |
| | | 7. If Unit or CA, Agreement Designation |
| 1. Type of Well Oil Sage Other | | 8. Well Name and No. |
| 2. Name of Operator | Attention: | Case B #10 |
| Amoco Production Company | Gail M. Jefferson, 1295C | 9. API Well No. |
| 3. Address and Telephone No. P.O. Box 800, Denver, Colorado | 80201 (303) 830-6157 | 3004520311 10. Field and Pool, or Exploratory Area |
| 4. Location of Well (Footage, Sec., T., R., M., or St | urvey Description) | Aztec Pictured Cliffs |
| 900FNL 1555FWL | Sec. 19 T 31N R 11W Unit C | 11. County or Parish, State |
| | | San Juan New Mexico |
| 2. CHECK APPROPRIA | TE BOX(s) TO INDICATE NATURE OF NOTICE, | REPORT, OR OTHER DATA |
| TYPE OF SUBMISSION | TYPE OF ACTION | |
| Notice of Intent Abandonment Recompletion Plugging Back Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Amoco Production Company requests permission to plug and abandon the above referenced well per the attached procedures. If you have any questions please contact Gail Jefferson at (303) 830-6157. | | |
| | DECEIVE N sep - 8 1995 OIL CON. DIV | RECEIVED BUM MAIL ROUM 95 AUS 32 AM IO: 54 070 FARMINGTON, NM |

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fluuduent statements

presentations as to any matter within its jurisdiction.

* See Instructions on Reverse Side

NMOCD

DISTRICT MANAGER

Case B #10 Orig. Comp. 8/68 TD = 2682', PBTD = 2672' Page 2 of 2

- 1. Blow down well. Kill if necessary with fresh water.
- 2. RU wireline. RIH with wireline and cement retainer. Set retainer at 2500'. Test casing integrity to 500#. Run short string CBL to determine TOC. Squeeze perfs at 2550' to 2688' with cuft cement. Pull up and spot cement to TOC.
- 3. RIH with perf gun and shoot squeeze holes at TOC and attempt to circulate to surface. Pull up and leave hole full to surface. If unable to circulate besure the following intervals are covered 100' inside and outside:

 Ojo Alamo at 899'
 and 675' to surface
- 4. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.