

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088

RECEIVED SEP 25 1996 OIL CON. DIV.

WELL API NO. 3004520749
5. Indicate Type of Lease STATE [ ] FEE [X]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Case LS
8. Well No. 11
9. Pool name or Wildcat Pictured Cliffs
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL [ ] GAS WELL [X] OTHER
2. Name of Operator Amoco Production Company Attention: Patty Haeefe
3. Address of Operator P.O. Box 800 Denver Colorado 80201 (303) 830-4988
4. Well Location Unit Letter I : 1800 Feet From The South Line and 1180 Feet From The East Line Section 19 Township 31N Range 11W NMPM San Juan County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [ ] TEMPORARILY ABANDON [ ] CHANGE PLANS [ ] PULL OR ALTER CASING [ ] OTHER: [ ]
SUBSEQUENT REPORT OF: REMEDIAL WORK [ ] ALTERING CASING [ ] COMMENCE DRILLING OPNS. [ ] PLUG AND ABANDONMENT [X] CASING TEST AND CEMENT JOB [ ] OTHER: [ ]

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company has plugged and abandoned this well per the following:

MIRUSU 9/12/96. Tried to pump down tubing at 2 bpm at 500 psi - bradenhead started to blow. (Note: NMOCD agreed to put CIBP and dump cement on plug and move in rig to find leak.) Tagged at 2460'. Set CIBP at 2450' and dumped 50' (2 sx) cement on CIBP. Est. TOC at 2400'. Run CBL from 190-2294'. Est. TOC at 1540'. Isolated leaks in casing at 773' and 1243'. Circulate to surface up bradenhead. Set cement retainer at 1021' and pump cement to surface inside and outside casing. Plugback 2410-1300'. Squeeze 2410-1300' with 30 sx Class B neat, 15.6 ppg. Set cement retainer at 1243-1021' and circulated cement to surface through casing leak at 1243', stung out and spotted cement to surface inside casing to plug and abandon well. Squeeze from 1243' - surface with 519 sx Class B neat, 15.6 ppg. Stung out of retainer and spotted 28 sx Class A neat, 15.6 ppg to surface. Cut off casing and capped and installed P&A marker on 9/16/96. RDMOSU 9/16/96.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Patty Haeefe TITLE Staff Assistant DATE 09-24-1996 TYPE OR PRINT NAME Patty Haeefe TELEPHONE NO. (303) 830-4988

(This space for State Use) APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE SEP 10 1997