representations as to any matter within its jurisdiction.

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135 Expires: March 31, 1993

5, Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS SF-078040 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation 1. Type of Well Oil Weil X Gee Weil Other 8. Well Name and No. Mudge A #30 2. Name of Operator 9. API Weil No. **Amoco Production Company** Dallas Kalahar 3. Address and Telephone No. 3004520887 (303) 830-5129 10. Field and Pool, or Exploratory Area P.O. Box 800, Denver, Colorado 80201 **Blanco Pictured Cliffs** 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec. 12 T 31N R 11W 870FNL 1550FEL San Juan **New Mexico** CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Notice of Intent **New Construction** Plugging Back Non-Routine Fracturing Subsequent Report Water Shut-Off **Final Abandonment Notice** (Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work . If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Amoco Production Company intends to plug and abandon the subject well per the attached procedures. 06-20-1994 Staff Business Analyst Approved by Conditions of approval, if any: Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States

* See Instructions on Reverse Side

NMOCD

GENERAL INSTRUCTIONS

This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning

the use of this form and the number of copies to be submitted particularly with regard to local area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

SPECIFIC INSTRUCTIONS

Item 4 - If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 13 - Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones,

or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of pacement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

NOTICE

The Privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et. seq., 351 et. seq., 25 U.S.C. et. seq.; 43 CFR 3160.

PRINCIPAL PURPOSE - The information is to be used to evaluate, when appropriate, approve applications, and report completion of secondary well operations, on a Federal or Indian lease.

ROUTINE USES:

- (1) Evaluate the equipment and procedures used during the proposed or completed subsequent well operations.
- (2) Request and grant approval to perform those actions covered by 43 CFR 3162.3-2(2)
- (3) Analyze future applications to drill or modify operations in light of data obtained and methods used.
- (4)(5) Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal, or regulatory investigations or prosecutions.

EFFECT OF NOT PROVIDING INFORMATION - Filing of this notice and report and disclosure of the information is mandatory once an oil or gas well is drilled.

The Paperwork Reduction Act of 1980 (44 U.S.C. 3501, et. seq.) requires us to inform you that:

This information is being collected in order to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

This information will be used to report subsequent operations once work is completed and when requested, to obtain approval for subsequent operations not previously authorized.

Response to this request is mandatory for the specific types of activities specified in 43 CFR Part 3160.


BURDEN HOURS STATEMENT

Public reporting burden for this form is estimated to average 25 m nutes per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management, (Alternate) Bureau Clearance Officer, (WO-771), 18 and C Streets, N.W., Wasington, D.C. 20240, and the Office of Management and Budget, Paperwork Reduction Project (1004-0135), Washington, D.C. 20503.

PXA Procedures Mudge LS #30

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. RIH with 1 1/4" workstring and cement retainer, set retainer at 2775'. Test casing integrity; y to 500#. Squeeze perfs at 2834' to 2868' with 5.31 cuft cement. Pull out of retainer and spot cement plug to 1560' with 10.552 cuft cement.
- 4. RIH with perf gun and shoot squeeze holes at 1500'. RIH with tbg and cement retainer, set retainer 50' above squeeze hole and attempt to circulate to surface with 170.455 cuft of cement. Pull out of retainer and displace cement to surface. (12.593 cuft cement)
- NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

Location - 128- 31N-11W SINGLE PC Orig.Completion = 7/72 Last File Update = 1/89 by DDM



Cathodic Protection - ?