Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction,

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT


FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICES AND I		Lesse Designation and Serial No. SF-078097 If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERM	1IT - " for such proposals	S. H. Haller, Associate St. Fride Name
		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Well Well Other		8. Well Name and No.
2. Name of Operator	Attention:	Heaton LS 28
Amoco Production Company	Julie L. Acevedo	9. API Well No.
3. Address and Telephone No.		3004520988
P.O. Box 800, Denver, Colorado 80201 (303) 830-6003		10. Field and Pool, or Exploratory Area
4. Location of Well. (Footage, Sec., T., R., M., or Survey Description)		Blanco PC ext.
1750FSL 1450FWL Sec.	25 T 31N R 11W	11. County or Parish, State
17301 3E 14301 WE 3ec.	25 7 5774 11 11 17	San Juan New Mexico
CHECK ADDRODDIATE DOVIAL T	O INDICATE NATURE OF NOTICE	DEPORT OF OTHER DATA
		
TYPE OF SUBMISSION	TYPE OF ACTIO	N
	Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
Final Abandanment Nation	Altering Casing	Conversion to Injection
Final Abandonment Notice	Other	Dispose Water Report results of multiple completion on Well Completion or
		eletion Report and Log form.)
Amoco Production Company intends to plug REGEIV SEP-1 1993 OIL CON. CON. COST. 3	ED	90 AUS 25 AUTO: 65
14.) hereby certify that the folegoing is true and correct Signed (This space for Fedgral or State office use)	Title Sr. Staff A	SSISTANT DATE 08-23-1993 APPROVED
Approved by Conditions of approval, if any:	Title	/AUG 27 1993
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly an representations as to any matter within its jurisdiction.	d willfully to make to any department or agency of the United S	TOTAL AND A TOTAL AND THE PARTY OF THE PARTY

PXA Procedures Heaton LS #28

- 1. Blow down well. Kill if necessary with fresh water.
- 2. RU wireline. Set cement retainer at 2540'. Test casing integrity to 500#. If okay RU cementer and pump truck. Establish injection rate through perfs at 2508' to 2606'. Spot cement plug to 1200'. (estimate 43.533 cuft)
- 3. If not MIRUSU. RIH with tbg and squeezes perfs at 2508' to 2606' with 31.029 cu ft cement. Pull out of retainer and spot cement plug to 2000'. (5.558 cuft) Isolate leak in casing, contact BLM, and see if furthur procedures are needed.
- 4. RIH with perforating gun and shoot squeeze holes at 1100'. (348.26 cuft) Attempt to circulate to surface through squeeze holes and displace cement to surface. (9.554 cuft)
- 5. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn well over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

HEATON LS 028 1394 Location - 25K- 31N-11W SINGLE PC Orig.Completion - 8/72 LAST FILE UPDATE - 12/92 BY CSW



UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 La Plata Highway Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 28 Heaton LS

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

,

- 2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made (when applicable):

1.) Set cement retainer 2 2450: (Toppert. 22508')

2.) In step 3, recalculate the cement volume spotted on top of the retainer.

3.) Perforate à 1176' instead of 1100'. (Bottom of Ojo Alamo à 1126')

Office Hours: 7:45 a.m. to 4:30 p.m.