UNITED STATES SUBMIT IN TRIPLICATE*

DEPARTMENT OF THE INTERIOR (Other Instructions on Fe-			5. LEASE DESIGNATION AND SERIAL NO. NM 6894	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTER OR TRIBE NAME	
OIL GAS WELL X OTHER			7. UNIT AGREEMENT NAME	
WELL WELL X OTHE 2. NAME OF OPERATOR	<u> </u>		8. FARM OR LEASE NAM	
JOHN E. SCHALK			LONE STAR INDUSTRIES SCHALK 94	
3. ADDRESS OF OPERATOR			9. WELL NO.	`.
P. O. BOX 2078, FARMINGTON, NEW MEXICO 87401 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1188 FROM THE SOUTH LINE, 1107 FROM THE WEST LINE			10. FIELD AND FOOL, OR WILDCAT PICTURED CLIFFS 11. SBC., T., R., M., OR BLE. AND SURVEY OR ARBA	
14. PERMIT NO.	15. SLEVATIONS (Show whether DF	C, RT, GR, etc.)	12. COUNTY OR PARISH	18. STATE NEW MEXICO
16. Check	Appropriate Box To Indicate N			NEW TIEX
			UBNT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING W	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	
REPAIR WELL	CHANGE PLANS	(Other) WELL	HISTORY	X
(Other)		(Nore: Report results	s of multiple completion of detion Report and Log for	on Well m.)
SPUDDED ON OCTO	·			
PERFORATIONS:	3815' TO 3880'	1 SHOT PER F	0 0T	**
	PERFORATED ON 11	-1-73	and the state of t	
	·			
			SEF > 7 by :	
18. I hereby certify that the bregot	is true the correct	OPERATOR	DATE 9-2	4- 74
(This space for Federal or State	office use)			

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: