## UNITED STATES SUBMIT IN TRIPLICATE. DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) UNITED STATES

GEOLOGICAL SURVEY

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

14-20-604-1951

San Juan

New Mexico

······································	
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NA

SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATE OF FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo & Ute Mountain			
1.	7. UNIT AGREEMENT NAME			
WELL GAS WELL OTHER	Horseshoe Gallup Unit			
2. NAME OF OPERATOR	8. FARM OR LEASE NAME			
Atlantic Richfield Company	Horseshoe Gallup Unit			
3. ADDRESS OF OPERATOR	9. WELL NO.			
501 Lincoln Tower Building, 1860 Lincoln St., Denver, Colo 80203	282			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT			
At surface	Horseshoe Gallup			
Unit "E" - 1975' f/North & 890' f/West lines Sec. 28	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA			
	Sec. 28-3: N-16W			
14. PERMIT NO. App d 15. ELEVATIONS (Show whether DF, 27. GR, etc.)	12. COUNTY OR PARISH 13. STATE			

Mr. McGrath, 6/1/74 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
				۱ ا		
TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL,		
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACIDIZE	ABANDON*	<u>                                     </u>	SHOOTING OR ACIDIZING	ABANDONMENT*		
REPAIR WELL	CHANGE PLANS		(Other) Spud, casing	g, drilling & Csg.	X	
(Orher)			(Note: Report results Completion or Recompl	of multiple completion on Well etion Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Moved in surface hole digger & spudded 12-1/hm hole @ 12 noon 7/18/74. Drld 12-1/hm hole to 120'. Ran 4 jts, 8-5/8"OD 32# casing set @ 118' GL, cemented w/ 100 ax Class "A" cmt, Cement circulted, job comp 3:15 pm 7/19/74. WOC. Wait on rotary to 8/1/74.

Moved in & rigged up rotary. Nip'd up head & BOP. Tested casing 8/1/74 725' Drilling. and BOP @ 900# for 30 minutes, held 0.K. Drld out 4 p.m. 8/1/74.

8/4/74 1561 WOC. Drilled to 1561. Ran logs. Ran 50 jts, 1550, 4-1/2 OD 9.5# J&K-55 casting w/ Baker guide shoe and float collar, 7 scratchers, 5 centralizers, set at 1561' KB, cemented w/125 ex B-J LO-Dense and 90 sx Class "A" neat cmt. Flug down 1:05 p.m. 8/3/74. Rel rig 2:30 pm 8/3/74.

Waiting on completion.



15.	I hereby certify that the foregoing is true and correct				***			·
	SIGNED Wa Walther Inf	TITLE	Dista	Prod. &	Drlg. Supt	DATE _	8/6/74	
;								
	This space for Federal or State office use)							
	APPROVED BYCOND: SOF APPROVAL, IF ANY:	TITLE				DATE _		