

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9706

4. Location of Well, Footage, Sec., T, R, M

1850' FNL, 1620' FWL, Sec. 35, T-31-N, R-9-W, NMPM

5. Lease Number
SF-078439

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number

Johnston Federal #6A

API Well No.

30-045-21642

10. Field and Pool

Blanco Mesaverde

11. County and State

San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☐ Abandonment

☐ Change of Plans

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☒ Other - Pay Add

13. Describe Proposed or Completed Operations

6-8-99 MIRU. TOOH w/rods & pump. ND WH. NU BOP. SDON.

6-9-99 TOOH w/2 3/8" tbg. TIH w/4 1/2" CIBP, set @ 4220'. Ran CBL-GR-CCL @ 4220-3500'; 100% bond. Ran TDT @ 4220-3500'. TIH w/4 1/2" pkr, set @ 2959'. PT csg & CIBP to 3500 psi/5 min, OK. TOOH w/pkr. TIH w/perf gun. Perf lower Lewis @ 4022-4172' w/120 0.46" diameter holes. SDON.

6-10-99 TIH w/junk mill, tag CIBP @ 4220'. TOOH w/mill. TIH w/4 1/2" RBP & pkr; set RBP @ 4210', set pkr @ 4138'. Brk dwn lwr Lewis perms w/300 gal 10% acetic. TOOH w/RBP & pkr. TIH w/pkr, set @ 2976'. SDON.

6-11-99 PT csg to 500 psi & lines to 8000 psi. Frac lwr Lewis w/770 bbl CO2, 45,000# 30/50 AZ snd. Flow back well. TOOH w/pkr. TIH w/CIBP, set @ 4000'. Perf upper Lewis @ 3737-3956' w/120 0.46" diameter holes. SDFW.

6-14-99 TIH w/RBP, set @ 3967'. PT CIBP to 3000 psi, OK. Brk dwn upper Lewis w/ 250 gal 10% acetic. Rls RBP & TOOH. TIH w/pkr, set @ 2975'. PT annulus to 500 psi & lines to 8000 psi. Frac upper Lewis w/866 bbl CO2, 450 sx 30/50 AZ snd. Flow back well.

6-15-99 Rls pkr & TOOH. TIH w/mill, tag up @ 3880'. CO to CIBP @ 4000'. Blow & flow well. SDON.

6-16-99 TIH to CIBP. Est circ & mill up plug. Chase plug & CO to CIBP @ 4220'. Circ & CO. Mill up CIBP, chase to PBTD @ 5210'. Circ hole clean. SDON.

6-17-99 TOOH w/mill. TIH w/166 jts 2 3/8" 4.7# J-55 tbg, set @ 5125'. ND BOP. NU WH. TIH w/one 2" x 1 1/4" x 10' Rhac pump & rods. PT & pump action OK. RD. Rig released.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 6/28/99
vkh

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any:

Date RECEIVED FOR RECORD