NO. OF COPIES RECEIVED		5	
DISTRIBUTION			
SANTA FE		1	
FILE		1	
U.\$.G.\$.			
LAND OFFICE	OFFICE		
IRANSPORTER	OIL	1	
INANSFORTER	GAS	7	
OPERATOR		1	
PRORATION OF	PRORATION OFFICE		
Operator			

· · · · · · · · · · · · · · · · · · ·				
DISTRIBUTION				
SANTA FE /		CONSERVATION COMMISSION	l	Form C-104
FILE /	REQUES	ST FOR ALLOWABLE		Supersedes Old C-104 and C Effective 1-1-65
		AND		Zincette 1-1-03
U.\$.G.\$.	AUTHORIZATION TO T	RANSPORT OIL AND NATUR	RAL GAS	
LAND OFFICE				
IRANSPORTER GAS /				
OPERATOR 1				
PRORATION OFFICE Operator				
Aztec Oil & Gas Com	pany			
P. O. Drawer 570, Fa	armington, New Mexico			
Reason(s) for filing (Check proper b	·	Other (Please explain	n)	
New Well	Change in Transporter of:	<u></u>		
Recompletion		Gas		
Change in Ownership	Casinghead Gas Con	densate		
change of ownership give name nd address of previous owner		,		
DESCRIPTION OF WELL AND	D LEASE   Well No.   Pool Name, Including	Formation Kind o	f Lease	Lease No
		State	Federal or Fee	]
Johns Location	1-A   Blanco Mesa	Verde Journe,		1.66
T)	B10 Feet From The North	Line and 1130 Feet	From The W	est
10	Township 32N Range		an Juan	Count
			an Juan	
DESIGNATION OF TRANSPO Name of Authorized Transporter of C	RTER OF OIL AND NATURAL	GAS		v of this form is to be sent)
Name of Wattionized Italiabotter of	Dil 🔲 💮 or Condensate 💢	Address (Give address to which	h approved copy	, of this form is to be sent)
	OII or Condensate X	,	• • • • • • • • • • • • • • • • • • • •	•
Plateau, Inc.		P. O. Box 108, Far	mington,	New Mexico
Plateau, Inc.	Casinghead Gas Or Dry Gas X	P. O. Box 108, Far	mington,	New Mexico y of this form is to be sent)
Plateau, Inc. Name of Author!zed Transporter of C El Paso Natural Gas	Casinghead Gas or Dry Gas X	P. O. Box 108, Far Address (Give address to which P. O. Box 990, Far	mington, happroved copy mington,	New Mexico y of this form is to be sent)
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids,	Casinghead Gas Or Dry Gas X	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected?	mington,	New Mexico y of this form is to be sent)
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks.	Casinghead Gas or Dry Gas X  Company  Unit Sec. Twp. Rge.	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected?	mington, happroved copy mington, When	New Mexico y of this form is to be sent)
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled	Casinghead Gas or Dry Gas X	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected?	mington, happroved copy mington, When	New Mexico y of this form is to be sent)
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks.	Casinghead Gas or Dry Gas X  Company  Unit Sec. Twp. Rge.	P. O. Box 108, Fare Address (Give address to which P. O. Box 990, Fare Is gas actually connected? No ol, give commingling order number	mington, happroved copy mington, When	New Mexico y of this form is to be sent) New Mexico
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled	Casinghead Gas or Dry Gas X  Company  Unit Sec. Twp. Rge.  with that from any other lease or por	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number	mington, happroved copy mington, When	New Mexico y of this form is to be sent) New Mexico
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, quive location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple	Casinghead Gas or Dry Gas X  Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Oil Well Gas Well  X	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number X	mington, happroved copy mington, When	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded	Casinghead Gas or Dry Gas X  Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number   New Well   Workover   Deep X   Total Depth	mington, happroved copy mington, When er:	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77	P. O. Box 108, Fare Address (Give address to which P. O. Box 990, Fare Is gas actually connected? No ol, give commingling order number   New Well   Workover   Deep   X	mington, happroved copy mington, When er: pen Plug	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc.	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay	mington, happroved copy mington, When er: pen Plug	New Mexico y of this form is to be sent) New Mexico  Back Same Res'v. Diff. Res 1. D
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, qive location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535 GR	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77	P. O. Box 108, Fare Address (Give address to which P. O. Box 990, Fare Is gas actually connected? No ol, give commingling order number   New Well   Workover   Deep   X	mington, happroved copy mington, When per: Plug 1 P.B.7	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc.  Name of Authorized Transporter of C  El Paso Natural Gas  If well produces oil or liquids, quive location of tanks.  If this production is commingled of COMPLETION DATA  Designate Type of Comple  Date Spudded  1-29-77  Elevations (DF, RKB, RT, GR, etc. 6535 GR  Perforations	Company  Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay	mington, happroved copy mington, When per: Plug 1 P.B.7	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, qive location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535 GR	Company  Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No  oil, give commingling order number New Well Workover Deep X	mington, happroved copy mington, When per: Plug 1 P.B.7	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M.	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? NO  ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay 4899	mington, happroved copy mington, When per: Plug 1 P.B.7	New Mexico y of this form is to be sent) New Mexico  Back Same Res'v. Diff. Res 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M. HOLE SIZE	Company  Unit Sec. Twp. Rge.  With that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? NO ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay 4899 AND CEMENTING RECORD DEPTH SET	mington, happroved copy mington, When per: Plug 1 P.B.7	New Mexico y of this form is to be sent) New Mexico  Back Same Res'v. Diff. Res 1 1.D. 5704 1 Gasing Shoe 5773  SACKS CEMENT
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4"	Company  Unit Sec. Twp. Rge.  With that from any other lease or portion—(X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay 4899 AND CEMENTING RECORD DEPTH SET 216.60	mington, happroved copy mington, When per: Plug 1 P.B.7	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res                 F.D.
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, qive location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M.  HOLE SIZE  13-3/4" 8-3/4"	Company  Unit Sec. Twp. Rge.  With that from any other lease or portion—(X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay 4899  AND CEMENTING RECORD DEPTH SET 216.60 3419.13	mington, happroved copy mington, When per: Plug 1 P.B.7	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4"	Company  Company  Unit Sec. Twp. Rge.  With that from any other lease or portion—(X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well   Workover   Deep X	mington, happroved copy mington, When per: Plug 1 P.B.7	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res                 F.D.
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"	Company  Company  Unit Sec. Twp. Rge.  With that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? NO ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay 4899 4899  AND CEMENTING RECORD DEPTH SET 216.60 3419.13 3284 -5773  5611	mington, happroved copy mington, When Per: Pen Plug I P.B.T	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL	Company  Company  Unit Sec. Twp. Rge.  With that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No  ol, give commingling order number New Well Workover Deep X	mington, happroved copy mington, When Plug   P.B.T  Tubin Depth	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, qive location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST	Company  Company  Unit Sec. Twp. Rge.  With that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No od, give commingling order number New Well Workover Deep X	mington, happroved copy mington, When Plug   P.B.T  Tubin Depth	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL Date First New Oil Run To Tanks	Company  Company  Unit Sec. Twp. Rge.  With that from any other lease or portion—(X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for this	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay 4899 4899  AND CEMENTING RECORD DEPTH SET 216.60 3419.13 3284'-5773' 5611' e after recovery of total volume of led depth or be for full 24 hours) Producing Method (Flow, pump,	mington, happroved copy mington, When Plug P.B.1 Tubin Depth	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL	Company  Unit Sec. Twp. Page.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for this	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No  ol, give commingling order number New Well Workover Deep X	mington, happroved copy mington, When Plug P.B.1 Tubin Depth	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL Date First New Oil Run To Tanks	Company  Company  Unit Sec. Twp. Rge.  With that from any other lease or portion—(X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for this	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X Total Depth 5774 Top Oil/Gas Pay 4899 4899  AND CEMENTING RECORD DEPTH SET 216.60 3419.13 3284'-5773' 5611' e after recovery of total volume of led depth or be for full 24 hours) Producing Method (Flow, pump,	mington, happroved copy mington, When Plug P.B.1 Tubin Depth	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL Date First New Oil Run To Tanks Length of Test	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for thise  Date of Test  Tubing Pressure	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X   Total Depth 5774   Top Oil/Gas Pay 4899   AND CEMENTING RECORD DEPTH SET 216.60 3419.13 3284   -5773   5611   e after recovery of total volume of total depth or be for full 24 hours) Producing Method (Flow, pump, Casing Pressure	mington, happroved copy mington, When Prescription Phase Prescription Phase Tubin Depth Depth Choke	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, qive location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc. 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL Date First New Oil Run To Tanks Length of Test  Actual Prod. During Test	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for thise  Date of Test  Tubing Pressure	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X   Total Depth 5774   Top Oil/Gas Pay 4899   AND CEMENTING RECORD DEPTH SET 216.60 3419.13 3284   -5773   5611   e after recovery of total volume of total depth or be for full 24 hours) Producing Method (Flow, pump, Casing Pressure	mington, happroved copy mington, When Prescription Phase Prescription Phase Tubin Depth Depth Choke	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL Date First New Oil Run To Tanks Length of Test	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for thise  Date of Test  Tubing Pressure	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X   Total Depth 5774   Top Oil/Gas Pay 4899   AND CEMENTING RECORD DEPTH SET 216.60 3419.13 3284   -5773   5611   e after recovery of total volume of total depth or be for full 24 hours) Producing Method (Flow, pump, Casing Pressure	mington, happroved copy mington, When Preserved P.B.1 Tubin Depth  Choke  Goat  Chil	New Mexico y of this form is to be sent) New Mexico  Back   Same Res'v.   Diff. Res
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL Date First New Oil Run To Tanks Length of Test  Actual Prod. During Test  GAS WELL  GAS WELL  Actual Prod. Test-MCF/D	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for this beable for this able for this control of the	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X	mington, happroved copy mington, When Preserved P.B.1 Tubin Depth  Choke  Goat  Chil	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res  1.
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, qive location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test  GAS WELL Actual Prod. Test-MCF/D 1956	Company  Unit Sec. Twp. Rge.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for this able for this able for this able.  Date of Test  Tubing Pressure  Length of Test  3 hrs	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X	mington, happroved copy mington, When Proved Plug l P.B.T  Tubin  Depth  Choke  Gravi	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res  1.
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, give location of tanks. If this production is commingled of COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M.  HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DII. WELL Date First New Oil Run To Tanks  Length of Test Actual Prod. During Test  GAS WELL Actual Prod. Test-MCF/D 1956 Testing Method (pitot, back pr.)	Company  Unit Sec. Twp. Page.  with that from any other lease or portion — (X)  Date Compl. Ready to Prod.  2-13-77  Name of Producing Formation  Mesa Verde  O.C.C.  TUBING, CASING, A  CASING & TUBING SIZE  9-5/8"  7"  4-1/2"  1-1/2"  FOR ALLOWABLE (Test must be able for this able	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X	mington, happroved copy mington, When Proved Plug l P.B.T  Tubin  Depth  Choke  Gravi	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res  1. D.  5704    19 Depth  5611    Casing Shoe  5773    SACKS CEMENT  190 SXS  170 SXS  245 SXS  It be equal to or exceed top all  19 of Condensate  Size  Size
Plateau, Inc. Name of Authorized Transporter of C El Paso Natural Gas If well produces oil or liquids, qive location of tanks. If this production is commingled to COMPLETION DATA  Designate Type of Comple Date Spudded 1-29-77 Elevations (DF, RKB, RT, GR, etc., 6535' GR Perforations See Form C-105 N.M. HOLE SIZE 13-3/4" 8-3/4" 6-1/4"  FEST DATA AND REQUEST DIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test  GAS WELL Actual Prod. Test-MCF/D 1956	Company    Unit   Sec.   Twp.   Ege.     with that from any other lease or portation - (X)   X     Date Compl. Ready to Prod.   2-13-77     Name of Producing Formation   Mesa Verde     O.C.C.   TUBING, CASING, A     CASING & TUBING SIZE   9-5/8"   7"     4-1/2"   1-1/2"     FOR ALLOWABLE   (Test must be able for this able	P. O. Box 108, Farm Address (Give address to which P. O. Box 990, Farm Is gas actually connected? No ol, give commingling order number New Well Workover Deep X Total Depth 5774¹ Top Oil/Gas Pay 4899¹  AND CEMENTING RECORD DEPTH SET 216.60 3419.13 3284¹-5773¹ 5611¹ e after recovery of total volume of led to the for full 24 hours) Producing Method (Flow, pump, Casing Pressure Water-Bbis.  Bbls. Condensate/MMCF Casing Pressure (Shut-in)	mington, happroved copy mington, When Plug P.B.1 Tubin Depth Choke Gravi Choke	New Mexico  y of this form is to be sent)  New Mexico  Back   Same Res'v.   Diff. Res  1. D.  5704    19 Depth  5611    10 Casing Shoe  5773    SACKS CEMENT  190 SXS  170 SXS  245 SXS  11 be equal to or exceed top all  10 Size  11 Size  12 Size  13 Size  14 Size  15 Size  16 Size  17 Size  18 Size  18 Size  19 Size

above is true and complete to the best of my knowledge and belief. District Production Hanager (Title) April 6, 1977

(Date)

This form is to be filed in compliance with RULE 1104.

SUPERVISON DANS. 30

TITLE .

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I, II, III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.