

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Aztec Oil & Gas Company

3. ADDRESS OF OPERATOR
P. O. Drawer 570, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
**1450' FSL & 1450' FEL
Section 15-31N-12W**

14. PERMIT NO. _____ 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6278' GR

5. LEASE DESIGNATION AND SERIAL NO.
SF-077651

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Richardson

9. WELL NO.
#12-A

10. FIELD AND POOL, OR WILDCAT
Blanco Mesaverde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 15-31N-12W

12. COUNTY OR PARISH 18. STATE
San Juan New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	CASING REPORT <input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-22-75 Ran 107 Joints Of 7" 23# K-55 Casing, Set Float Shoe At 4700', Stage Tool Set At 2979'. Cemented First Stage With 120 Sacks Of 65/35, 12% Gel, 1/2# Cello Flake, 50 Sacks Of Class "B" & 2% Chloride. Plug Down At 4:00 PM. Cemented Second Stage With 280 Sacks Of 65/35, 12% Gel, 1/2# Cello Flake, 50 Sacks Of Class "B" & 2% Chloride. Plug Down At 5:30 PM.

10-24-75 Ran 19 Joints Of 4 1/2" 10.50# K-55 Casing, Float Shoe Set At 5250', Hanger Set At 4635'. Cemented With 100 Sacks Of Class "C". Plug Down At 3:30 AM.

RECEIVED
OCT 29 1975
U. S. GEOLOGICAL SURVEY
FARMINGTON, N.M.

RECEIVED
OCT 30 1975
OIL CON. COM.
DIST 3

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE District Superintendent DATE October 28, 1975

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: