

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

## Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator

**BURLINGTON  
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

790' FSL, 1750' FEL, Sec. 11, T-31-N, R-10-W, NMPM

5. Lease Number

SF-078389A

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

San Juan 32-9 Unit

8. Well Name & Number

San Juan 32-9 U #44A

API Well No.

30-045-28940

10. Field and Pool

Blanco Mesaverde

11. County and State

San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

## Type of Submission

## Type of Action

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - Pay Add	

13. Describe Proposed or Completed Operations

4-1-99 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg. TIH w/4 1/2" CIBP & pkr. Pre-set CIBP @ 3273'. Unable to work free. TOOH w/pkr. SDON.

4-2-99 TIH w/3 7/8" mill, tag CIBP. D/O CIBP, chase to 5597'. TOOH w/mill. TIH w/3 7/8" mill, est circ. Rotate mill @ 3265-3278'. TIH to 4600'. Blow well @ 4600'.

4-3-99 Blow well. TOOH w/mill. TIH w/4 1/2" CIBP, set @ 4530'. TIH w/4 1/2" pkr, set @ 4437'. PT CIBP to 4300 psi, OK. Rls pkr & TOOH. TIH. Perf Lewis w/2 SPF @ 4190-4440' w/120 0.46" diameter holes total. TIH w/4 1/2" pkr, set @ 4059'. Brk dwn perfs w/1300 gal 10% acetic. Rls pkr & TOOH. SDFW.

4-5-99 TIH w/4 1/2" pkr, set @ 3237'. SDON.

4-7-99 PT csg to 1000 psi, lines to 8000 psi, OK. Frac Lewis w/125 tons CO2, 35,000# 20/40 AZ snd. Rls pkr & TOOH. TIH w/4 1/2" CIBP, set @ 4150'. Perf 2<sup>nd</sup> stage Lewis w/2 SPF @ 3804-4054' w/110 0.46" diameter holes total. SDON.

4-8-99 TIH w/4 1/2" RBP & pkr, set @ 4100'. PT CIBP to 4300 psi/15 min, OK. Brk dwn perfs. Rls RBP, TOOH w/RBP & pkr. TIH w/4 1/2" pkr, set @ 3237'. PT lines to 7500 psi, OK. Frac 2<sup>nd</sup> stage Lewis w/175 tons CO2, 55,000# 20/40 AZ snd. Flow back well.

4-9-99 Rls pkr & TOOH. TIH w/3 7/8" mill, tag up @ 3997'. Blow well & CO. D/O CIBP @ 4150'. Flow well naturally.

4-10/11-99 Flow well.

4-12-99 TIH, tag up @ 4450'. CO @ 4450-4520'. D/O CIBP @ 4530'. CO to PBTD @ 5703'. Blow well. Flow well naturally.

4-13-99 TOOH w/mill. TIH w/181 jts 2 3/8" 4.7# J-55 tbg, set @ 5657'. ND BOP. NU WH. RD. Rig released.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 4/27/99

vkh

(This space for Federal or State Office use)

APPROVED BY

Title

Date

CONDITION OF APPROVAL, if any: