

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

October 5, 1984

Mr. Cecil Bell Southern Union Exploration Co. P.O. Box 2179 Farmington, NM 87499

Re: Susco 16 #1 M-16-32N-8W

Dear Cecil;

Annual packer test on the referenced well was inconclusive in proving zone separation.

Please reschedule and retest the well in such a manner as to prove zone separation. Shut both zones in for a minimum of 3 days. Blow the higher pressured zone to the atmosphere for as long as it takes to get a significant pressure drop. Please advise this office at least 24 hours prior to the test, so we may provide a witness.

Yours truly,

Charles Gholson

Deputy Oil & Gas Inspector

CG/dj

cc: Well File