UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Noti	ces and Reports on Wells. 2	77	
-	1777 BW ZZ 111 Z Z		Lease Number
	CTO FASSANIGTON, N		SF-078115
m 6 wall	CIO EVARIMICATORA	6.	
Type of Well		建筑	Tribe Name
GAS			
		7.	Unit Agreement Na
Name of Operator	- Williams	المام المام المام والمام المام والمام والمام والمام والمام والمام والمام المام المام المام المام المام والمام المام	
	IN DEC 2 4		
BURLINGTON		DIVIO	
TESCETTEES OIL	E GAS COMPANY	्र •्रि 8.	Well Name & Number
		(*)	Grenier #13E
Address & Phone No. of Operat	ior (505) 336 9700		API Well No.
PO Box 4289, Farmington, NM	87499 (505) 326-9700	J.	30-045-25332
		10	Field and Pool
Location of Well, Footage, So		10.	Basin Dakota M
1760'FNL, 1520'FWL, Sec.20, '	I-31-N, K-II-W, NMPM	17	County and State
		***	San Juan Co, NM
			Dail 02
Subsequent Report Final Abandonment	Casing Repair Waltering Casing	Non-Routine Water Shut o Conversion t	ff
	X Other -		
Describe Proposed or Comp It is intended to recompl	ete the subject well accord	ding to the	attached procedure
igned IAAA ALC This space for Federal or State	Title Regulatory Admin	istrator Dat	<u> </u>
PPROVED BY	Title	Date _	12/20/77
ONDITION OF APPROVAL, if any:			
ahdt			

NMOCD

District I PO Box 1980, Hobbs, NM 88241-1980 District II PO Drawer DD, Artesia, NM 88211-0719

State of New Mexico Energy, Minerals & Natural Resources Department

Form C-102 Revised February 21, 1994 Instructions on back

OIL CONSERVATION DIVISION

Submit to Appropriate District Office

District III 1000 Rio Brazos Rd., Aztec, NM 87410 PO Box 2088 Santa Fe, NM 87504-2088 22 TV 2: 22 State Lease - 4 Copies
Fee Lease - 3 Copies

District IV PO Box 2088, Santa Fc, NM 87504-2088 ON NOT AMENDED REPORT

Ceruficate Number

FRANKETON, NM WELL LOCATION AND ACREAGE DEDICATION PLAT Pool Nume ¹ Pool Code API Number Blanco Mesaverde/Basin Dakota 72319/71599 30-045-25332 ' Well Number Property Name * Property Code 13E Grenier 18530 * Elevation 1 Operator Name OGRID No. 6104' GR Burlington Resources Oil & Gas Company 14538 ¹⁰ Surface Location East/West line County North/South line Feet from the Feet from the Lot Ida Township Range Section UL or lot no. SJ 1520 West 1760 North 11W 31N 20 11 Bottom Hole Location If Different From Surface County East/West line North/South line Feet from the Lot Ida Feet from the Township Range UL or let no. Section 13 Dedicated Acres 13 Joint or Infill 14 Consolidation Code 15 Order No. W/320NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION 17 OPERATOR CERTIFICATION I hereby certify that the information contain true and complete to the best of my knowledge and belief Original plat from Fred B. Kerr Jr. 1-8-82 Peggy Cole 15201 Regulatory Administrator 18SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by mi or under my supervision, and that the same is true and correct to the best of my belief. Date of Survey Signature and Seal of Professional Surveyer:

SUNDRY NOTICE SUBMITTAL

1999 MOV 22 FM 2: 22

OF FRANCION, IN

Well: Grenier #13E

Unit E, Sec. 20, ~31N, R11W San Juan, NM

It is intended to recomplete the Mesaverde formation in the existing Dakota wellbore. A rig will MIRU, ND wellhead, NU BOP, and pull production tubing. A CIBP will be set above the Dakota formation at approximately 5474'.

If adequately isolated by cement, the Mesaverde will be perforated and fracture stimulated in two stages in the following interval: 4450' - 5374' cement remediation operations are necessary, Burlington Resources will contact the appropriate regulatory agency for approval prior to work initiation.

After stimulation flowback, the CIBP above the Dakota will be drilled out and tubing will be landed approximately 100' above PBTD. The well will then produce commingled production for the Mesaverde and Dakota formations. Application for commingling will be submitted.

Approved:

Drilling Superintendent