Form 9-331 (May 1963)	DEPAR	UNITED STATES TMENT OF THE INTE		5. LEASE DESIGNATION AND SERIAL NO.
	e this form for pro	OTICES AND REPORT	S ON WELLS	8. IF INDIAN, ALLOTTEE OR TRIBE NAME
	AS OTHER	7. UNIT AGREEMENT NAME		
2. NAME OF OPERA		8. FARM OR LEASE NAME Navajo 'F'		
3. ADDRESS OF OP	ERATOR	9. WELL NO.		
4. LOCATION OF W See also space At surface	ELL (Report locatio			155 10. FIELD AND POOL, OR WILDCAT  Horseshoe Gallup 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA  9-31N-17W
14. PERMIT NO.		15. ELEVATIONS (Show whether	er df, at, gr, etc.) 5210 'GL	San Juan New Mexico
16.	Check A	• • •	e Nature of Notice, Report, or C	Other Data DENT REPORT OF:
TEST WATER S FRACTURE TRE SHOOT OR ACIL REPAIR WELL (Other)	AT	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other) SPUD (Note: Report results Completion or Recompl	REPAIRING WELL ALTERING CASING ABANDONMENT*  of multiple completion on Well letion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

SPUDDED 12 Noon, 7/12/82, U.S.G.S. contacted by phone.

•			
18. I hereby certify that the foregoing is true and correct			
Signed Sherwin Artus	TITLE	Vice President	DATE July 13, 1982
Sherwin Artus			
(This space for Federal or State office use)			
APPROVED BY	TITLE		ggspress hecono

**NMOCC** 

\*See Instructions on Reverse Side