

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-87

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|                                                                                                     |
|-----------------------------------------------------------------------------------------------------|
| WELL API NO.<br><b>30 045 25476</b>                                                                 |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No.                                                                        |

|                                                                                                                                                                                                                             |                                                               |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)                       |                                                               |
| 1. Type of Well:<br>Oil <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER                                                                                                                         | 7. Lease Name or Unit Agreement Name<br><b>Keys Gas Com G</b> |
| 2. Name of Operator<br><b>Amoco Production Company Attn: John Hampton</b>                                                                                                                                                   | 8. Well No.<br><b>1</b>                                       |
| 3. Address of Operator<br><b>P.O. Box 800, Denver, Colorado 80201</b>                                                                                                                                                       | 9. Pool name or Wildcat<br><b>Frutland Coal</b>               |
| 4. Well Location<br>Unit Letter <b>K</b> : <b>1480</b> Feet From The <b>South</b> Line and <b>1620</b> Feet From The <b>West</b> Line<br>Section <b>27</b> Township <b>32N</b> Range <b>10W</b> NMPM <b>San Juan</b> County |                                                               |
| 10. Elevation (Show whether DF, RXB, RT, CR, etc.)<br><b>5962' KB</b>                                                                                                                                                       |                                                               |

|                                                                                                         |                                                      |
|---------------------------------------------------------------------------------------------------------|------------------------------------------------------|
| 11. Check Appropriate Box to Indicate Nature of Notice. Report of Other Done<br>NOTICE OF INTENTION TO: |                                                      |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                                                          | PLUG AND ABANDON <input checked="" type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/>                                                            | CHANGE PLANS <input type="checkbox"/>                |
| PULL OR ALTER CASING <input type="checkbox"/>                                                           | OTHER: <input type="checkbox"/>                      |
| REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>                         |                                                      |
| COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>          |                                                      |
| CASING TEST AND CEMENT JOB <input type="checkbox"/>                                                     |                                                      |
| OTHER: <input type="checkbox"/>                                                                         |                                                      |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company intends to Plug and Abandon the subject well.  
See attached for procedure:

If you have any questions please call Julie Acevedo at 303-830-6003

|                                                                                                          |                                                       |
|----------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. |                                                       |
| SIGNATURE <b>JL Hampton/CEB</b>                                                                          | TITLE <b>Sr. Staff Admin. Supv</b> DATE <b>5/3/90</b> |
| TYPE OR PRINT NAME                                                                                       | TELEPHONE NO.                                         |


(This space for State Use)

Original Signed by **CHARLES G. HANSON** SECURITY OF & GAS INSPECTOR, DIST. # **MAY 07 1990**  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

PROCEDURE  
KEYS GAS COM /G/ #1

1. Check Bradenhead, casing and tubing pressures
2. MIRUSU
3. Install BOP
4. Pressure test wellbore and CIBP to 1000 psig.
  - a. If the test passed, proceed with step 5.
  - b. If the test doesn't pass, TOH with tubing, pickup packer, TIH, and determine if there is a casing or CIBP leak. Call office.
5. Drill out CIBP at 2639'. Clean out hole to 2644' (top of fish), make a scraper run if necessary. Attempt to establish a rate into the open hole. TOH
6. TIH with retainer and set at 2600'. Pump 50 sacks of class G neat cement through retainer. Stage last 3 bbl and dump 2 bbl on top of retainer. Be precise with cement volumes; we don't want to damage the Keys Gas Com /G/ No. 1R. TOH
7. Spot 600' cement plugs back to surface.
8. Cut off casing, weld plate with Inscribed wellname and location, and finish PxA operations according to state regulations.

KEYS GAS COM /G/ #1  
T32N R10W SEC 27 SW  
SAN JUAN COUNTY, NEW MEXICO  
GLE 5949' KB 5962'



FILENAME:  
KEYSG104/90