

September 26, 1984

Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410

Gentlemen:

The following is the deviation record for Southland Royalty Company's Reese Mesa #10 well located in Section 10, T32N, R8W, San Juan, New Mexico.

| <u>Depth</u> | <u>Deviation</u> | <u>Depth</u> | Deviation |
|--------------|------------------|--------------|-----------|
| 500' | 3/4 deg. | 2100' | 1/2 deg. |
| 1000' | 1 deg. | 2603' | 1/2 deg. |
| 1100' | 1/2 deg. | 3050' | 1 deg. |
| 1516' | 1/2 deg. | 3698' | 1 deg. |
| 1970' | 3/4 deg. | 4130' | 3/4 deg. |

Sincerely,

SOUTHLAND ROYALTY COMPANY

R. E. Fielder

District Production Manager

REF/eg

Attachment

Oil Conservation Division Page Two September 26, 1984



STATE OF NEW MEXICO

County of San Juan

The foregoing instrument was acknowledged before me this 26th day of September, 1984, by R. E. Fielder of Southland Royalty Company on behalf of said Company.

NOTARY BOND FILED WITH SECRETARY OF STATE

My Commission Expires: 4-27-85

Esther J& Greyeyes Notary Public - NM

> OIL CON. DIV. DIST. 3