

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP (ATE)
(Other Instructions
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Wintershall Corporation

3. ADDRESS OF OPERATOR
5251 DTC Parkway, Suite 500, Englewood, CO 80111

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
945' FNL & 1110' FWL (NWNW)

5. LEASE DESIGNATION AND SERIAL NO.
MOO-C-1420-4387

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Ute Mtn. Ute

7. UNIT AGREEMENT NAME
N/A

8. FARM OR LEASE NAME
Ute Mtn. Ute

9. WELL NO.
34-11

10. FIELD AND POOL, OR WILDCAT
Basin Dakota

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA
34-31N-14W

14. PERMIT NO.
API#: 300458715500

15. ELEVATIONS (Show whether OF, RT, GR, etc.)
5543' ungraded ground

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☒
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

10/9/87 MIRU Completion rig.
10/10/87 Ran CBL & Press test csg to 3000 psi. Held OK.
10/11/87 Perforate Burro Canyon from 5708-5713'.
10/12/87 Acidize Burro Canyon w/ 500 gal. 15% HCL.
10/13/87 Swabbing salt water
10/16/87 Set Bridge plug @ 5687' & tested to 3000 psi.
10/17/87 Perforate Dakota w/ 15 holes @ 5559, 62', 65', 68', 72', 74', 78', 82', 84', 99',
5603', 13', 16', and 19'. Acidized with 1000 gals 15% HCL acid. Fractured with
93,460 gals slick water and 52,800# 20/40 sand.
10/18/87 - 10/27/87 Swab & flow back load fluid.
10/27/87 SI for pressure build up.

RECEIVED
DEC 09 1987
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED David P. Howell TITLE Operations Manager

(This space for Federal or State office use)

DATE 10/29/87

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

OPERATOR'S COPY

*See Instructions on Reverse Side