

F

30-045-27069

9-12-88

F. Loc. 1660N;1180E Elev. 6191 GL Spd. Comp. ID Cu. ft. PB
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ T Gas
 Csg. Perf. Prod. Stim.

Grav. 1st Del. Gas
 I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS	NIID X	Well Log	TEST DATA							Ref.No.
Ojo Alamo	C-103	Plot X	Schd.	PC	Q	PW	PD	D		
Kirtland	C-104	Electric Log								
F. Kirtland		C-122								
Pictured Cliffs	Ditr	Dfa								
Chacra	Datr	Dac								
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

N/319.85
 Acres 159.30

R-8768
 Basin Fr. Coal Co. SJ S 9 T 31N R 10W U H Oper. MERIDIAN OIL INC. Lse. LUCERNE A COM No. 101

LUCERNE A COM#101

H-09-31N-10W

MERIDIAN OIL INC.

SF-079634 (WC) et al.
3162.3-1(F) (019)

MAR. 19 1990

RECEIVED
MAR 20 1990
OIL CON. DIV.]
DIST. 3

Meridian Oil Incorporated
Southland Royalty Company
P. O. Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells.

Southland Royalty Company

1✓ No. T501 McClanahan, 1450' FSL & 1190' FWL, sec. 13 T. 28 N., R. 10 W.,
San Juan County, New Mexico, lease SF-079634.

Meridian Oil Incorporated

1✓ No. 506 Murphy Com, 1850' FSL & 1180' FWL, sec. 24, T. 30 N., R. 11 W., San
Juan County, New Mexico, lease SF-080113.

2✓ No. 506⁴ Morris A Com, 1150' FNL & 1155' FEL, sec. 15, T. 30 N., R. 11 W.,
San Juan County, New Mexico, lease SF-078138.

3✓ No. 101 Lucerne A Com, 1660' FNL & 1180' FEL, sec. 9, T. 31 N., R. 10 W.,
San Juan County, New Mexico, lease SF-078389.

1✓ No. 102 Lucerne A, 1450' FSL & 1730' FWL, sec. 9, T. 31 N., R. 10 W., San
Juan County, New Mexico, lease SF-078389.

5✓ No. 700 Lloyd C, 790' FNL & 790' FEL, sec. 11, T. 29 N., R. 11 W., San
Juan County, New Mexico, lease NM-03877.

6✓ No. 800 Lloyd A, 1770' FNL & 1850' FEL, sec. 9, T. 29 N., R. 11 W., San
Juan County, New Mexico, lease NM-03486-A.

The subject APDs are rescinded and returned pursuant to your written instructions dated November 29, 1989.

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in an assessment of liquidated damages.

Sincerely,

Ken Townsend

John L. Keller
FOR Chief, Branch of Minerals

7 Enclosures

cc:

NMOCD, Aztec