

30-045-27079

9-14-88

F

F. Loc. 845S:960W Elev. 6020 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
S

I.P. _____ BO/D _____ MCF/D After _____ Hrs. _____ SICIP _____ PSI After _____ Days GOR _____		Grav. _____ 1st Del. Gas _____		1st Del. Oil _____						
TOPS		NITD X	Well Log	TEST DATA						
			Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Ojo Alamo		C-103	✓✓							
Kirtland		C-104								
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

Acres 5/322.54
161.38

R-8768

Basin Fr. Coal Co. SJ S 17 T 31N R 10W UM Oper. SOUTHLAND ROYALTY CO. HUDSON COM No. 200

HUDSON COM#200

M-17-31N-10W

SOUTHLAND ROYALTY CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
1235 LAPLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401



IN REPLY REFER TO:

SF-078487 (WC)
3162.3-1.0 (019)

CERTIFIED - RETURN RECEIPT REQUESTED
P 253 046 165

DEC. 13 1990

Southland Royalty Company
P.O. Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

1. No. 200 Hudson Com, SW/4SW/4 sec. 17, T. 31 N., R. 10 W.,
San Juan County, New Mexico, lease SF-078134.
2. No. 103 Trail Canyon, SE/4NE/4 sec. 18, T. 32 N., R. 8 W.,
San Juan County, New Mexico, lease NM-33055.
3. No. 103 Reese Mesa, NW/4SE/4 sec. 11, T. 32 N., R. 8 W.,
San Juan County, New Mexico, NM-6890.
4. No. 210 Hill, SE/4NE/4 sec. 4, T. 29 N., R. 8 W.,
San Juan County, New Mexico, lease SF-078487.

As discussed with Peggy Bradfield of your company on October 12, 1990, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date and within the second six month extension period.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

ABANDONED LOCATION

1st John L. Keller

Ron Fellows
FOA Area Manager

RECEIVED
DEC 14 1990
OIL CON. DIV.
DIST. 3

cc:
NMOCD, 1000 Rio Brazos Road, Aztec, NM 87410