Form 11 su-5 December 1444.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-1135

Expires September 30. 1440

5 Lease Designation and Serial No.

Water Shut-Off

(Note: Report results of multiple completion on Well Completion or

CO 2 Stimulation

Conversion to Injection

SUNDRY NOTICES AND REPORTS ON WELLS	1 4211	4.4	SF 080517
			5 If Indian, Allone
m for proposals to drill or to deepen or recent to a			

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. idian. Allonee or Tribe Name Use "APPLICATION FOR PERMIT-" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Oul Someth 8. Well Name and No. 2. Name of Operator Holmberg Gas Com D Amoco Production Company Attn: John 1 9. API Well No 3. Address and Telephone No. 30 045 27208 P.O. Box 800, Denver, Colorado 80201 10 Field and Pool, or Exploratory Area 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) edar Hill Fruit. SEP 0 4 1990 790' FNL x 1610' FEL, SEC. 21, T32N-R10W 11. County or Parish, State OIL CON. DIV. San Juan, New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF AGTICE, REPORT, OR OTHER DATA 12 TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing

Recompletion Report and Log form 1

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally druled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Amoco Production Company intends to stimulate well by pumping liquid ${\rm CO}_2$ down well

- 1. MIRUSU.
- 2. Set on location 120 tons of liquid CO2.
- 3. Pump ${\rm CO_2}$ down casing/tubingannulus @ 2 BPM, with the last 100 BBL to be pumped @ a minimum breakdown rate of 10 BPM. SI
- 4. Allow CO₂ to soak for 2 days.

Final Abandonment Nouce

- 5. Place well on test for a minimum of 2 weeks.
- 6. Well will then be evaluated for pipeline hookup or abandonment.

Note: Production test should be conducted while holding the flowing tubing pressure @ a constant 350 psi.

14. I hereby certify that the foresome is			
14. I hereby ceruly that the foregoing is true and correct Signed Aman Tonk		Admin. Supv.	120/90
(Thus specy for Federal or State office use) Approved by Conditions of approval, if any:	Tide	AUG 3 0 1990	
	MOCT	AREA MANAGER	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States and false. Sectionis or Irandicipolis